

1064

PAGE 1 OF 1 #884298261

OFFENSE REPORT

1. Offense INFORMATION		2. Classification ACCIDENTAL DEATH		IN 0740010	SS 09	17	1737
3. Location of Incident DIVIDEN BRIDGE RD LAST RES. ON D-WAY				4. Zone 2	5. Date/Time Occurred 09-17-88 1737		6. Date/Time Police Arrived 09-17-88 1737
7. Victim STEVEN C. WINFREY	Sex M	Race W	D.O.B. N/A	8. Home Address WILSON ST. GREENBRIER TN		9. Phone	
10. Business Address N/A		11. Business Phone N/A		12. Person Arrested N/A		Sex	Race
13. Complainant WALTER PHILLIP		Sex	Race	D.O.B.	14. Home Address RT #2 BOX 301 GOODLETTSVILLE		15. Phone
16. Witnesses' Name		Sex	Race	D.O.B.	17. Home Address		18. Phone
19. VEHICLE		a. License No. (LIC)	b. State	c. Year	d. Type	e. Vehicle Identification No. (VIN)	f. Year
1. Style		2. Color	3. Other Description or Damage				
20. WEAPON		Gen. Description		Serial # (SN)	Make	Caliber	Type
21. PROPERTY		Description					22. Total Value
23. Reporting Officer HILLIARD, CHARLES				Badge 436AT	Unit 536	24. Approving Supervisor	
25. NARRATIVE: Give All Information Necessary. Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witnesses' Names, Sex, Race, D.O.B., Addresses And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.							
<p>ON SEPT. 17-88 AT 5:37 PM. WHILE ON DIVIDEN BRIDGE ROAD A SUBJECT FLAGGED ME DOWN AND STATED THAT THEIR 4 BOY THATS DOWN AND WAS STOP BREATHING. AT THIS TIME MYSELF AND OFFICER RANDY CAUENDER WENT INSIDE THE RESIDENT AND FOUND A WHITE MALE JUVENILE IN THE FLOOR WITH SEVERAL SUBJECTS WERE AROUND THE KID. AT THIS TIME A NEIGHBOR STATED THAT THE YOUNG BOY GOT INTO AN ELECTRIC FENCE THAT WAS INSIDE THE DOG PEN. OFFICER CAUENDER AND ANOTHER SUBJECT IDENTIFIED AS PAM OLSON STARTED C.P.R. ON THE SUBJECT WHILE I DISPATCHED THE AMBULANCE SERVICE, RIDGETOP FIRE DEPT. AND VANDERBILT'S LIFE-FLIGHT TO THE SCENE. APPROX 15 MIN LATER THE AMBULANCE ARRIVED AND TOOK OVER C.P.R. UNTIL LIFE FLIGHT ARRIVED. JUST A SHORT TIME AFTER LIFE FLIGHT WAS IN ROUTE TO VANDERBILT HOSPITAL WITH THE SUBJECT.</p> <p>THE OWNER OF THE RESIDENT STATED THAT THE MOTHER OF THE 4 YEAR OLD BOY, NANCY WINFREY LEFT THE CHILD AT HIS RESIDENT WHILE SHE WENT BACK HOME MR. PHILLIP STATED THAT THE KIDS WERE OUTSIDE PLAYING AND THEY NOTICED THAT THEY DID NOT SEE STEVEN (THE VICTIM) PLAYING WITH THE OTHER KIDS. THEY GOT UP AND LOOKED OUT AND SAW STEVEN LYING OVER INSIDE THE DOG PEN OVER THE ELECTRIC FENCE.</p>							
END OF PAGE ONE							
STATUS		Active <input type="checkbox"/>	Pending <input type="checkbox"/>	Inactive <input type="checkbox"/>	Closed <input type="checkbox"/>	Assigned To	
NCIC/TIES Entries Have Been Made By:		Date		All Items Have Been Cleared From NCIC/TIES By:		Date	

PAGE 1-OF 1

209

PAGE 2-OF-1 #884298261

OFFENSE REPORT

PAGE 2-OF-1

1. Offense INFORMATION		2. Classification ACCIDENTAL DEATH		TN 074000	38 YEAR	09 MONTH	17 DAY	1737
3. Location of Incident PAGE 1 OF 1				4. Zone 2	5. Date/Time Occurred 09-07-88		6. Date/Time Police Arrived 09-17-88	
7. Victim PAGE 1 OF 1		Sex	Race	D.O.B.	8. Home Address			9. Phone
10. Business Address		11. Business Phone		12. Person Arrested			Sex	Race
13. Complainant		Sex	Race	D.O.B.	14. Home Address			15. Phone
16. Witness' Name		Sex	Race	D.O.B.	17. Home Address			18. Phone
19. VEHICLE		a. License No. (LIC)	b. State	c. Year	d. Type	e. Vehicle Identification No. (VIN)	f. Year	g. Make
1. Style		j. Color		k. Other Description or Damage				
20. WEAPON		Gen. Description		Serial # (SN)	Make	Caliber	Type	
21. PROPERTY		Description						22. Total Value
23. Reporting Officer WILLARD, CHARLES			Badge 567	Unit 540	24. Approving Supervisor			
25. NARRATIVE: Give All Information Necessary, Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witness' Names, Sex, Race, D.O.B., Addresses And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.								
<p>MR PHILLIP RAN OUT BACK, GOT THE BOY AND BROUGHT HIM INSIDE THE RESIDENT JUST AS WE PULLED INTO THE DRIVEWAY. MR. PHILLIP AND I WENT OUT TO THE DOG PEN TO LOOK AT THE FENCE AND HE STATED THAT THE FENCE WAS A 24 VOLT ELECTRIC FENCE THAT WAS PUT INSIDE THE DOG PEN TO KEEP THE DOGS AWAY FROM THE MAIN FENCE. THE MAIN FENCE STANDS ABOUT 3 1/2 FT. WITH THE ELECTRIC FENCE ABOUT A FOOT FROM THE GROUND ON THE INSIDE.</p> <p>THE MOTHER, NANCY WINEREE WAS NOTIFIED AND WAS TRANSPORTED TO VANDY'S HOSPITAL BY HER BROTHER. MRS. WINEREE'S DAUGHTER WAS AT THE RESIDENT AT THE TIME WITH MR. AND MRS. PHILLIPS.</p> <p>MYSELF AND DEP. CAUENDER LEFT THE SCENE AT 6:32 P.M. AND AT 7:19 I RECEIVED A CALL FROM VANDERBILT HOSPITAL AND WAS TOLD THAT THE 4 YEAR OLD WHITE MALE JUVENILE DID NOT MAKE IT.</p>								
<div style="text-align: right;">210</div>								
STATUS		Active <input type="checkbox"/> Pending <input type="checkbox"/> Inactive <input type="checkbox"/> Closed <input type="checkbox"/>		Assigned To		Authority		Date

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven Dewayne Winfrey

ADDRESS: P.O.Box 303, Greenbrier Tenn 37073

PHONE NUMBER: None

NARRATIVE: On 9/23/88, Mrs Wanda Winfrey came to the sheriffs dept. There I interviewed her concerning the recent death of her son shown above. I was told by her that some of the information contained in the reports where not accurate.

"INVESTIGATIVE NOTE" The mothers name on the previous reports show the mothers name as Nancy Winfree, which is incorrect in both first name and spelling of last name. Original reports should reflect the name of Wanda Winfrey as the mother of the victim. Further the victims name was also incorrect in which the previous reports show the victims name as Steven C Winfree, The reports should reflect the name of Steven Dewayne Winfrey.

Further it was learned that the mother of victim is the sister of Walter Phillips, She (Wanda Winfrey) further told me that she did not have any type of insurance coverage on the victim that would pay in case of death, She (Wanda Winfrey) further signed a affidavit giving Vanderbilt Hospital permission to release all medical records concerning the victim to this agency.

(When all information is obtained and this file completed, Mrs Winfrey wishes that a complete copy of this file be mailed to her at the above adress)

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☒


CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/23/88

211

INVESTIGATIVE REPORT

Case No 88-4298-261				
TN0740000	88	09	17	1737
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven C Winfree DOB/ 9/24/84

ADDRESS: Wilson Street, Greenbrier Tenn

PHONE NUMBER: None

NARRATIVE: On 9/19/88, I recieved a copy of an offense report from Det Sgt Green, the report showed that the above victim had died from an electrical shock from a fence at the Phillips residence located on dividing ridge road in Ridgetop Robertson County Tenn. A summary shown on the report by Patrol Sgt Hilliard showed that he and officer Cavender where on patrol in the area when they where flagged to stop by a subject on a three wheeler and told that a young boy had stoped breathing at the Phillips residence, according to the report they arrived at the residence to find the child unconciouse and found him not to be breathing where Deputy Cavender and a niighbor began C.P.R. on the child while Sgt Hilliard Called for further assistance. Hilliard further revealed in his report that the victims mother Nancy winfree droped the child off at the residence earlier that day and that he and the other children where playing in the back yard area of the residence when a short while later he (Walter Phillips) noticed that the victim was not playing with the other children when he went to investigaye he found the child on the inside of the dog pen laying over the electric fence that lines the inner side of the dog pen. At that Time the child was taken into the house by family members and afterwards he was flown out to Vanderbuilt Hospital by Life Flight. Hilliards report further stated that he recieved a call

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

[Signature]
 CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: from officials (unknown accordind to the report) from
Vanderbilt Hospital that told him that the child died.

..... INVESTIGATORS NOTE : On 9/19/88 I recieved this information
as previously described, an investigator was not notified at the time
of the incident therefor the following information was obtained by
myself during a follow up investigation some 48 hours later.

On 9/19/88 I furter spoke with officer Cavender who also
was at the scene of the incident, he could not add any further imfor-
mation other than it appeared that Mr Phillips or someone at the res
idence had possibly been cunsuming some alcoholic type beverages for
there was a couple of budweiser cans setting on a table at the rear
porch area where they said they where setting, Further that Mr Phill
ips looked according to the reddish complexion to the face to have
had a few beers but did not appear to Cavender to be intoxicated.
Further that he (Cavender) observed the dog pen and from his memory
he told me that he belives that there where two stands of electrical
fence wire around the inner side of the pen, further that one of the
m was approximatly one foot from the ground, Cavender further told m
e that he observed a burn or bruise mark on the leg of the child tha
t appeared to have been caused by a wire or some type. He further
told me that there was no other marks such as bruising or laceration
s or contusions that he saw on the body of the child and that he :

STATUS: ACTIVE ☐PENDING ☐INACTIVE ☐CLOSED ☐

CRIMINAL INVESTIGATOR

ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

213

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: was dressed in a pair on sneakers, short pants and shirt.
After speaking with Deputy Cavender, I drove to the location
of the incident where I observed the residence, It being a small
white frame hose having a front and rear concrete porch area, furthe
r having an add on onning type car port to the west side of the resi
dence, further having a small wooden storage shed located directly
to the rear of the back porch of the residence being approximatly
15 feet from the porch, further the before mentioned dog pen was
located to the rear of the shed attatched to the rear of the shed
The pen was made of wooden post placed approximately 8 to 9 feet apart
having what appeared to be 36 inch by 4X4 farming fence attatched
on the outer side of the post and to the rear of the shed. The meas
urements of the pen where approximately 36 foot deep and 42 feet in
width, measurements where stepped off being 12 steps by 14 steps.
I furter examined the described pen and was unable to locate the
electric wireing as described by Sgt Hilliard in his report or by
Deputy Cavender whom I had previously talked with. I further observe
d two chow dogs that occupy the pen. Afterwards I walked to a neigh
bors residence located due west of the residence, there I spoke with
a White male and female who told me that they where at home when the
incident occured but that they where mowing the yard and did not know
that anything had occured until the emergency vehicles had began to

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

214

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: arrive at the residence. They further told me that the entire family was at the funeral home at the time of my visit and further that since the incident that Mr Phillips had taken the electric fence down. Afterwards I went back to the residence where I obtained my camera and photographed the residence, shed and dog pen described earlier. Further a Mr Winfree, app 18 Y.O.A. arrived at the residence and was obviously grief stricken by the death of his younger brother, he took me to the rear of the residence and took out a control box that operated the electric fence and gave it to me and further told me that I was welcome to look around the residence if I wished, further that he was not at the residence the day of the incident but that his uncle (Mr Phillips) was also very upset as to what had happened. Afterwards I took the control Box to my unit where I examined it closely and further photographed it. and afterwards listed all pertinent information as follows:

Produced by: FIDO-SHOCK inc. 5360 National Drive, Knoxville Tenn, 37914.

"Solid State Pet Deterent electric fence controller". Power by 110-120 Volt, 60 Hz Ac. "DANGER" Any Alterations to the designe of this charger may cause seriouse electrical shock. Further showes an intermittent output of current and showes to be used with 12 to 20 quage wire only. Model # SS-750. also below is a square silver sticker with B-6 labeled on it. The device is U/L listed No. 11N0. Serial

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

215

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: No. G-04346, also a code No. 305-159 in the lower left corner. Also in the lower center of the device is a label listed "Use 1/16 Amp time delay fuse only." I further upon examining the two fuses contained in the device found them to be 1/4 Amp, 250 Volt No. 313 each both showing manufacturer code as L F Fuse. Both fuses being four times the strength recommended by the manufacturer.

After leaving the Phillips residence, I returned to my office where I called the Vanderbuilt Emergency room to find out what the results of the autopsy that I understood that they had performed. I was told by a nurse there that they did not perform an autopsy; the body was sent to the metro medical examiners office. Afterwards I contacted the medical examiners office where I spoke with Doctor Simpkins. He further told me that he did not perform an autopsy that the body was brought to there office simply for record purposes only. He further told me that the probable cause for death was cardiac arrest due to an electrical shock. he further told me that the victim had a small burn on the left posterior wrist, also to the rear of the right knee joint. Doctor Simpkins further told me that he did not examine the victim that he recieved his information from the Vanderbuilt Emergency room report and he further was unable to tell me the Doctor name who examined the victim.

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

1. Smith
 CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT

9/19/88

216

INVESTIGATIVE REPORT

Case No. 88-4298-261				
TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: Afeterwards I obtained the name and phone number of the Doctor who was a Dr Brian Gibler, Phone No. 353-0327. I called Mr Gibler and after he verified my position I asked him pertinent ques tions about the victim. He told me that the child was brought into the emergency room in full cardiac arrest and that hte family told him that the child had been shocked by an electric fence. He further told me that the family was obviously grief stricken and that he did not suspect any foul play. He further told me that he could not offer any information as to the crime scen itself but that there was a burn mark on the leg of the victim and that it appeared that it could have been caused by an electrical fence. I further ask the Doctor if a small amperage such as the before mentioned control box could have caused the childs heart from beating. he then told me that he was not familiar with electricity and that it was the first case of this nature that he had seen but that all he knows is that an electrical shock can and on some occasions will stop the heart from beating. I was unable to obtain any further information from Dr Gibler. After speaking with him I prepared an authorization for medical information release form in wich I plan to have a family member signe and obtain all medical records pertaining to this case.

STATUS:ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐

Robertson
CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven Dewayne Winfrey

ADDRESS: P.O.Box 303, Greenbrier Tenn 37073

PHONE NUMBER: None

NARRATIVE: On 9/23/88, Mrs Wanda Winfrey came to the sheriffs dept. There I interviewed her concerning the recent death of her son shown above. I was told by her that some of the information contained in the reports where not accurate.

"INVESTIGATIVE NOTE" The mothers name on the previous reports show the mothers name as Nancy Winfree, which is incorrect in both first name and spelling of last name. Original reports should reflect the name of Wanda Winfrey as the mother of the victim. Further the victims name was also incorrect in which the previous reports show the victims name as Steven C Winfree. The reports should reflect the name of Steven Dewayne Winfrey.

Further it was learned that the mother of victim is the sister of Walter Phillips. She (Wanda Winfrey) further told me that she did not have any type of insurance coverage on the victim that would pay in case of death. She (Wanda Winfrey) further signed a affidavit giving Vanderbilt Hospital permission to release all medical records concerning the victim to this agency.

(When all information is obtained and this file completed, Mrs Winfrey wishes that a complete copy of this file be mailed to her at the above adress)

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☒

[Signature]
CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/23/88

68 A0117

NASHVILLE, TN.....
 BANNER.....
 9/12/88

15

21 Greenbrier 4-year-old dies after shock from fence

From Banner staff reports

GREENBRIER — A 4-year-old Greenbrier boy died Saturday around 7:30 p.m. after he apparently stumbled into an electric fence and was severely shocked, according to Robertson County Sheriff's deputy Charles Hillard.

The child, Steven C. Winfree, and his sister were visiting the home of Walter Phillip of Dividing Ridge Road in Greenbrier about 23 miles north of Nashville.

Phillip told police the boy was playing with some other children about 5:30 p.m. Saturday in the backyard when he

stumbled into an electric fence inside a dog pen.

The 24-volt electric fence is used, Phillip said, to keep the dogs away from the fence surrounding the pen.

The child, the son of Steven Carl and Wanda Winfree of Maple Street, was taken by the Lifeflight helicopter to Vanderbilt University Medical Center, where he later died.

While on their way to the scene, Robertson County Emergency Medical Service workers notified Vanderbilt about the situation.

The emergency helicopter flew to the scene and landed in the neighborhood, according to

Robertson County Emergency Service Director Bob Fletcher.

"The sheriff's deputy was already on the scene so they started CPR," Fletcher said.

Winfree's body has been taken to Nashville General Hospital to be examined, Vanderbilt officials said today.

Robertson County Chief Deputy Milton Frederick said the department is still investigating the incident.

"We'll probably have a comprehensive report later today," Frederick said.

Frederick said officials are investigating to see if the fence was operating properly when the child fell on it.

Epd. 5

OCT 31 1988

8811150002060

219

ACCIDENT INVESTIGATION REQUEST FORM

Document Number R8A0117A1

Date of Incident 9/17/88 Category I.D. SECT1519F9

Follow-up Requested Hazard Analysis ☐ Section 15 ☒

Type Follow-up Requested Telephone Call ☐ On-Site ☐

Headquarters Contact Dave Johnson 492-6608

Assignment Message Conduct an investigation of the electric fence related death reported in the attached news article. Contact local officials for information on the product, the accident location and the circumstances (malfunctions of unit). Obtain a copy of any report regarding this death, including that of any analysis of the product.

Person(s) to Contact Co. Sheriff Det Charles Helms
Robertson Co. Sheriff Det
William Frederick
Greenbrier, Tenn

Guideline _____

Requested By Russell

Task Number 881115000 2060

Assigned to Chi Date 11/15/88

FIELD ACTIVITY COVERSHEET

1. REGION/STATE FOCR/ATL-SO		2. OPERATION (Check One) <input type="checkbox"/> Inspection <input type="checkbox"/> Establishment Visit <input type="checkbox"/> Telephone Contact <input checked="" type="checkbox"/> Investigation <input type="checkbox"/> Other _____		3. DATE 12/01/88	
				4. NUMBER (For RO Use) 881115CCC2060	
5. ESTABLISHMENT Name <u>Fi-SHOCK, Inc.</u> Address <u>530 National Drive</u> City <u>Knoxville</u> State <u>TN</u> Zip <u>37914</u> Telephone No. <u>(615) 524-7384</u>					
6. RELATED FIRM <input type="checkbox"/> Parent <input type="checkbox"/> Headquarters <input type="checkbox"/> Subsidiary <input type="checkbox"/> Other Name _____ City _____ State _____					
7. PRODUCTS COVERED <u>FIDO SHOCK Pet Deterrent</u>			8. OTHER CONSUMER PRODUCTS <u>N/A</u>		
9. ESTABLISHMENT TYPE N/A <input type="checkbox"/> Manufacturer <input type="checkbox"/> Importer <input type="checkbox"/> Wholesaler <input type="checkbox"/> Own Label Distributor <input type="checkbox"/> Retailer <input type="checkbox"/> Repackager <input type="checkbox"/> Other _____			10. ANNUAL PRODUCTION N/A Products Covered \$ _____ Units _____ Other Products \$ _____ Units _____		
11. I.S. BUSINESS N/A % Received _____ % Shipped _____		12. SAMPLES COLLECTED None		13. MIS CODE 32626	
14. HOURS Activity <u>14</u> Travel <u>4</u>					
15. REASON FOR ACTIVITY (Assignment Reference) In Depth Investigation #881115CCC2060					
16. EMPLOYEE'S NAME David M. Galanti		TITLE PSI		SIGNATURE <i>David M. Galanti</i>	
17. <input checked="" type="checkbox"/> ENDORSEMENT <input type="checkbox"/> REMARKS <input type="checkbox"/> SUMMARY <input type="checkbox"/> OTHER <p>A 4 year old boy was electrocuted when he fell across an electric "Pet Deterrent" fence. There were no witnesses to the incident. The victim's adult relatives found the victim after they had missed him from playing for a few minutes.</p> <p>The victim's uncle installed the electrically charged fence. When the uncle was putting the fence up he found that the recommended 1/16 amp fuses would blow each time power was supplied to the control box. The victim's uncle inserted 2-1/4 amp fuses into the control box and the fence worked. The victim's aunt stated that the only way to get the fence to work was to use stronger fuses than those recommended.</p> <p>The electric fence had been discarded at the time of the investigation. The investigator was unable to obtain the control box as a sample and for examination due to possible future litigation. F/U: An inspection of the manufacturer will be assigned.</p>					
18. REVIEWER'S NAME George L. Lester		TITLE SPSI		SIGNATURE <i>George L. Lester</i>	
19. REVIEW DATE 1/25/89		DISTRIBUTION O: EPDS, cc: FOCR Inv file, ATL (LGG), CACA, cs: LGG, GLL, RF			

1. CASE NO.			2. INVESTIGATOR'S ID			3. OFFICE CODE			<h2 style="margin: 0;">EPIDEMIOLOGIC INVESTIGATION REPORT</h2>		
881115CCC2060			8 9 3 5			8 3 8					
4. DATE OF ACCIDENT			5. DATE INVESTIGATION INITIATED			6. SYNOPSIS OF ACCIDENT OR COMPLAINT					
YR MO DAY 8 8 0 9 1 7			YR MO DAY 8 8 1 2 0 6			<p>A four year old male victim died of Cardiac/Respiratory arrest after receiving an electric shock by falling across a electric dog fence. The victim was playing "frisby" with his cousin and was attempting to retrieve the toy which had inadvertently gone over the fence. Examination of the controller for the electric dog fence identified two fuses which were four times the strength recommended for use by the manufacturer.</p>					
7. LOCATION (Home, school, etc.)				8. CITY				9. STATE			
Home - Back Yard				1 1 Ridge Top				Tennessee T N			
10A. FIRST PRODUCT				11A. TRADE/BRAND NAME, MODEL NUMBER, MANUFACTURER & ADDRESS							
Electric Wire				"FIDO-SHOCK", Model #SS-750 FI-Shock Inc., 5360 National Drive, Knoxville, TN							
10B. SECOND PRODUCT				11B. TRADE/BRAND NAME, MODEL NUMBER, MANUFACTURER & ADDRESS							
None				N/A							
12. AGE OF VICTIM			13. SEX (Use numerical code)			14. DISPOSITION			15. INJURY DIAGNOSIS		
0 0 4			MALE - 1 FEMALE - 2 UNKNOWN - 3 1			Fatality 8			Electric Shock 6 7		
16. BODY PART			17. RESPONDENT(S) (Mother, Friend)			18. TYPE INVESTIGATION			19. TIME SPENT		
All Parts			8 5 Police Detective			ON SITE 1 TELEPHONE 2 OTHER 3 1			1 4 0		
20. ATTACHMENTS			21. CASE SOURCE			22. REVIEWED BY			23. REGIONAL OFFICE DIRECTOR REVIEW		
Multiple			9 Newspaper			8 2 9 8			8 9 0 1 2 5		
23. PERMISSION TO DISCLOSE NAMES											
(NON-NEISS CASES ONLY) CPSC MAY DISCLOSE MY NAME <input type="checkbox"/> CPSC MAY NOT DISCLOSE MY NAME <input checked="" type="checkbox"/>											
24. NARRATIVE (See instructions on Other Side)						25. REGIONAL OFFICE DIRECTOR REVIEW					

(USE OTHER SIDE AND ADDITIONAL SHEETS IF NECESSARY)

881115CCC2060

Pre-Accident:

This investigation was conducted in response to a newspaper report that a four year old male child died as a result of injuries received after he fell across a electric dog fence. Information gained in this case was obtained through an on-scene examination of the accident area, and conversations with the victim's aunt and police officials.

Victim's aunt stated that her husband purchased the entire electric dog fence system approximately one year ago at Lowe's Building and Supply, Clarksville, Tennessee. The electric fence was installed by victim's uncle inside of a existing dog compound that measured approximately 36 feet by 42 feet. The purpose of the electric fence was to prevent two Chow dogs from jumping up on the inside of the pre-existing fence and climbing out of their enclosure. The electric dog fence consisted of two strands of electrical fence wire attached to wooden stakes approximately one foot from the inside of the pre-existing fence. The bottom wire of the electric fence was approximately one foot from the ground and the top wire was approximately three feet from the ground.

Victim's aunt stated that the victim was approximately four feet tall and weighed approximately fifty pounds. Victim had brown hair and brown eyes. Victim was a very active child and had a history of bronchitis. Victim's mother brought the victim to their house in order for him to play with his cousin. Victim was wearing tennis shoes, a pull-over "T" shirt and short pants at the time of the accident. Victim's mother was not present at the time of the accident.

At approximately 5:15 pm, September 17, 1988, victim was playing "Frisby" with his three year old cousin in the back yard. Weather conditions were cloudy and overcast, and the temperature was approximately 75 degrees fahrenheit. It had rained earlier in the day and the ground was still wet.

Accident:

At approximately 5:30 pm, victim's uncle, who was sitting on his back porch, noticed that the victim was no longer in sight. Victim was discovered by his uncle inside of the dog compound slumped across the electric dog fence, but not in contact with the outside pre-existing fence. Victim was unconscious and a burn mark was observed behind his right knee.

881115CCC2060

Post Accident:

Victim's uncle immediately picked up victim (without being shocked) and carried him into the house. A county police patrol responded to the location and attempted to revive the victim by Cardio Pulmonary Resuscitation (CPR). Victim was subsequently transported to Vanderbilt Hospital, Nashville, Tennessee where he was pronounced dead. Cause of death, as reported by the medical examiner, was identified as cardio/respiratory arrest due to electric shock and the manner of death identified as accidental.

Victim's uncle subsequently removed both strands of the electric dog fence and threw them away, however, the electrical control box was not discarded and was taken by county police detectives for examination. Their examination revealed the existence of two fuses, 1/4 Amp, 250 Volts each, inserted in the control box. It was observed from the labeling on the control box panel that both of the fuses that were used in the control box were four times the strength recommended by the manufacturer. Victim's aunt stated that when her husband was putting up the fence he attempted to use the fuses that came with the electric fence system, however, each time the recommended fuses were used the fuses would "blow" as soon as power was supplied to the control box. Victim's aunt stated that the only way to get the fence to work was to use stronger fuses.

A request was made by the CPSC investigator to obtain the control box for a sample and examination however, due to possible future litigation, the request was refused.

Telephonic contact with Lowe's Building and Supply, Clarksville, Tennessee revealed that they no longer had the Fido-Shock, pet deterrent in stock, and they have not experienced any product complaints

Standards:

No voluntary or mandatory standards information was observed on the product.

Product Identification:

The product is an electrical control box enclosed in black plastic and generally mounted indoors, on the walls of a building. Product is manufactured by Fi-SHOCK, Inc., 5360 National Drive, Knoxville, Tennessee, 37914. Additional labeling states: FIDO-SHOCK, Solid State Pet Deterrent, Electric Fence Controller. The controller is powered by 110-120 Volt 60Hz ac. Additional warnings include: "DANGER" any alterations to the design of this charger may cause serious electrical shock. At top center of the box a warning states "use one sixteenth Amp time delay fuses only"

No assembly instructions or additional warnings information was available.

881115CCC2060

Attachments:

1. Photographs
2. Medical Examiners Investigative Report, dtd 9/18/88
3. Robertson County Offense Report, dtd 9/17/88
4. Investigation Report, dtd 9/19/88
5. Newspaper Article, 9/19/88 (Nashville Banner)
6. Copy of CPSC Assignment

METROPOLITAN NASHVILLE
AND DAVIDSON COUNTY
OFFICE OF THE MEDICAL EXAMINER
FORENSIC SCIENCES CENTER
84 HERMITAGE AVENUE
NASHVILLE TN 37210-2110
(615) 259-6920

CASE NO. MEC 88-1666

REPORT OF INVESTIGATION BY COUNTY MEDICAL EXAMINER

DECEASED Steven Winfree RACE: W SEX: M AGE: 3
First name Middle name Last name D O B 9-24-84

HOME ADDRESS P O Box 303 Greenbriar Tn M W S D OCCUPATION: _____
Number and Street City or County State

TYPE OF DEATH: Violent ☐ Casualty ☒ Suicide ☐ Suddenly when in apparent health ☐ Found Dead ☐
(Check one only) In Prison ☐ Suspicious, unusual or unnatural ☐ Cremation ☐

Comment electric shock

If Motor Vehicle Accident Check One: Driver ☐ Passenger ☐ Pedestrian ☐ Unknown ☐

Notification by Dr. Ann Byers / Vandy ER 322-0145 Address Nashville

Investigating Agency M. P. D.

DESCRIPTION OF BODY: Clothed ☐ Unclothed ☐ Partly Clothed ☐ Circumcised Yes ☐ No ☐


Eyes Brown : Hair Brown : Mustache _____ : Beard _____

Weight 38.6 : Length 40 : Body Temp _____ : Date and Time 9/17/88
Pounds inches Fahrenheit

Rigor: Yes ☒ No ☐ Lysed ☐ Livor Color _____ Fixed ☐ Non-Fixed ☐

Marks and Wounds _____

Cyanosis



PROBABLE CAUSE OF DEATH

MANNER OF DEATH

DISPOSITION OF CASE

Cook's. Reps. Arrest.
due to Electric Shock.
from Dog Fence.

(Check one only)

Accident ☒ Natural ☐
Suicide ☐ Unknown ☐
Homicide ☐ Pending ☐

1. Not a medical examiner case ☐

2. Autopsy requested Yes ☐ No ☐

Autopsy ordered Yes ☐ No ☐

Pathologist _____

I hereby declare that after receiving notice of the death described herein I took charge of the body and made inquiries regarding the cause of death in accordance with Section 38-701-38-714 Tennessee Code Annotated; and that the information contained herein regarding such death is true and correct to the best of my knowledge and belief.

9-18-88

Date

County of Appointment

Donna C. Harlan, M.D. E. Simpson, M.D.

Signature of County Medical Examiner

226

PERSONAL HISTORY: Suicide attempts ☒ Suicide threats ☐ Hobbies, aptitude, skills with firearms, chemicals, etc. ☐
 Domestic, premarital or marital conflicts ☐ Financial or business reverses ☐ Social or religious conflicts ☐ Legal difficulties ☐
 Cults ☐ Criminal record ☐ Unemployment ☐ Fear of disease ☐ Other (specify) _____

CONDUCT BEFORE DEATH: Efforts to prevent help ☐ Efforts to obtain help ☐ Suicide attempt: Admitted ☐ Denied ☐
 Refusal to talk ☐ Written declaration of intended suicide ☐ Accusations against others ☐ Other (specify) _____

DATE	LAST SEEN ALIVE	INJURY OR ILLNESS	DEATH	DISCOVERY	MEDICAL EXAMINER NOTIFIED	VIEW OF BODY	POLICE NOTIFIED
9-17-88	9-17-88	9-17-88	9-17-88		9-17-88	9-17-88	Same
TIME	1700	± 1700	1904		1925	1300	
LOCATION		CITY OR COUNTY		TYPE OF PREMISES (HOSPITAL, HOTEL, HIGHWAY, ETC.)			
INJURY OR ONSET OF ILLNESS		Davidson		Residence			
DEATH		Vanderbuilt ER		Hospital			
VIEWING OF BODY BY MEDICAL EXAMINER		F S C		Davidson County Morgue			

MEDICAL ATTENTION AND HOSPITAL OR INSTITUTIONAL CARE

NAME OF PHYSICIAN OR INSTITUTION	ADDRESS	DIAGNOSIS	DATE

CIRCUMSTANCES OF DEATH

NAME	ADDRESS
FOUND DEAD BY	
LAST SEEN ALIVE BY	
WITNESS TO INJURY OR ILLNESS AND DEATH	
N O K FH	(Mother- Wanda Winfree) Cole & Garrett 865-6164

NARRATIVE SUMMARY OF CIRCUMSTANCES SURROUNDING DEATH:

HX- A three year old baby was life flown from Greenbriar Tenn to V U M C. The patient had an electrical shock received from a vent. He was coded for approximately 40 minutes then died. The baby was born at Vanderbuilt and has been there several times for various reason but has no personal Doctor.

@ P.R. & therapy, no response began in 2 R U and 1823.

Continued demanding 1901 (see Card record on this sheet)

Electrical Burn small area. Left foot wrist area. & larger longer Burn area behind at knee joint on leg. response to therapy Negative. (no other evidence of trauma.)

Cardi/Respiratory Arrest due to Electric fence shock.

(Blood drawn for toxicology.) No urine available
 Happen at Ducking Ridge Rd. Robertson County - 2nd home

1004

PAGE 1-OF-1 #884298261

OFFENSE REPORT

1. Offense INFORMATION		2. Classification ACCIDENTAL DEATH		TH 0740-3	50	09	17	1737
3. Location of Incident DUNEDRIDGE RD LAST RES ON D-WALKER				4. Zone	5. Date/Time Occurred 09-17-88 1737		6. Date/Time Police Arrived 09-17-88 1737	
7. Victim STEVEN C. WINFREY	Sex M	Race W	D.O.B. N/A	8. Home Address WILSON ST. GREENBRIER TN		9. Phone		
10. Business Address N/A		11. Business Phone N/A		12. Person Arrested N/A		Sex	Race	D.O.B.
13. Complainant WALTER PHILLIP		Sex	Race	D.O.B.	14. Home Address RT #2 BOX 301 GOODLETSMILL		15. Phone	
16. Witness' Name a.		Sex	Race	D.O.B.	17. Home Address a.		18. Phone a.	
19. VEHICLE NONE		a. License No. (LIC)	b. State	c. Year	d. Type	e. Vehicle Identification No. (VIN)	f. Year	g. Make
h. Model		i. Other Description or Damage						
20. WEAPON		Gen. Description		Serial # (SN)		Make		Caliber
21. PROPERTY		Description		Serial # (SN)		Make		Type
22. Reporting Officer HILLIARD, CHARLES		Badge 436AT		Unit 436		24. Approving Supervisor		
24. NARRATIVE Give All Information Necessary. Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witness' Names, Sex, Race, D.O.B., Addresses And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.								
<p>ON SEPT. 17-88 AT 5:37 PM WHILE ON DUNEDRIDGE ROAD A SUBJECT FLAGGED ME DOWN AND STATED THAT THERE'S A BOY THAT'S DOWN AND HAS STOP BREATHING. AT THIS TIME MYSELF AND OFFICER RANDY CAUENDER WENT INSIDE THE RESIDENT AND FOUND A WHITE MALE JUVENILE IN THE FLOOR WITH SEVERAL SUBJECTS WERE AROUND THE KID. AT THIS TIME A NEIGHBOR STATED THAT THE YOUNG BOY GOT INTO AN ELECTRIC FENCE THAT WAS INSIDE THE DOG PEN. OFFICE CAUENDER AND ANOTHER SUBJECT IDENTIFIED AS PAM OLAN STARTED C.P.R. ON THE SUBJECT WHILE I DISPATCHED THE AMBULANCE SERVICE, RIDGETOP FIRE DEPT., AND WANDERBILT'S LIFE-FLIGHT TO THE SCENE. APPROX 15 MIN LATER THE AMBULANCE ARRIVED AND TOOK OVER C.P.R. UNTIL LIFE FLIGHT ARRIVED. JUST A SHORT TIME AFTER LIFE FLIGHT WAS IN ROUTE TO WANDERBILT HOSPITAL WITH THE SUBJECT.</p> <p>THE OWNER OF THE RESIDENT STATED THAT THE MOTHER OF THE 4 YEAR OLD BOY, NANCY WINFREY LEFT THE CHILD AT HIS RESIDENT WHILE SHE WENT BACK HOME. MR. PHILLIP STATED THAT THE KIDS WERE OUTSIDE PLAYING AND THEY NOTICED THAT THEY DID NOT SEE STEVEN (THE VICTIM) PLAYING WITH THE OTHER KIDS. THEY GOT UP AND LOOKED OUT AND SAW STEVEN LYING OVER INSIDE THE DOG PEN OVER THE ELECTRIC FENCE.</p>								
END OF PAGE ONE								
STATUS		Active <input type="checkbox"/> Pending <input type="checkbox"/> Inactive <input type="checkbox"/> Closed <input type="checkbox"/>		Assigned To		Authority		Date
NCIC/TIES Entries Have Been Made By:		Date		All Items Have Been Cleared From NCIC/TIES By:		Date		

PAGE 1-OF-1

PAGE 2-OF-1 #884298261

1. Offense INFORMATION		2. Classification ACCIDENTAL DEATH		3. Date/Time Occurred 07/14/2000		4. Date/Time Police Arrived 09-17-88		5. Date/Time Police Arrived 09-17-88	
3. Location of Incident PAGE 1 OF 1		4. Zone 2		5. Date/Time Occurred 09-07-88		6. Date/Time Police Arrived 09-17-88		7. Phone	
7. Victim PAGE 1 OF 1		8. Sex		9. Race		10. D.O.B.		11. Home Address	
10. Business Address		11. Business Phone		12. Person Arrested		13. Sex		14. Race	
13. Complaint		14. Sex		15. Race		16. D.O.B.		17. Home Address	
14. Witness' Name		15. Sex		16. Race		17. D.O.B.		18. Home Address	
15. Vehicle		16. License No. (LIC)		17. State		18. Year		19. Type	
16. Style		17. Color		18. Other Description or Damage		19. Vehicle Identification No. (VIN)		20. Year	
20. Weapon		21. Gen. Description		22. Serial # (SN)		23. Make		24. Caliber	
21. Property		22. Description		23. N/A		24. Total Value		25. N/A	
22. Reporting Officer WILLARD, CHARLES		23. Badge SGT		24. Unit 540		25. Approving Supervisor		26. N/A	
24. NARRATIVE: Give All Information Necessary, Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witnesses' Names, Sex, Race, D.O.B., Address And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.									
MR. PHILLIP RAN OUT BACK, GOT THE BOY AND BROUGHT HIM INSIDE THE RESIDENT JUST AS WE PULLED INTO THE DRIVEWAY. MR. PHILLIP AND I WENT OUT TO THE DOG PEN TO LOOK AT THE FENCE AND HE STATED THAT THE FENCE WAS A 24 VOLT ELECTRIC FENCE THAT WAS PUT INSIDE THE DOG PEN TO KEEP THE DOGS AWAY FROM THE MAIN FENCE. THE MAIN FENCE STANDS ABOUT 3 1/2 FT. WITH THE ELECTRIC FENCE ABOUT A FOOT FROM THE GROUND ON THE INSIDE.									
THE MOTHER, NANCY WINEREE WAS NOTIFIED AND WAS TRANSPORTED TO VANDERBILT HOSPITAL BY HER BROTHER. MRS. WINEREE'S DAUGHTER WAS AT THE RESIDENT AT THE TIME WITH MR. AND MRS. PHILLIPS.									
NIXON AND DEP. LAQUENOR LEFT THE SCENE. AT 6:32 P.M. AND AT 7:19 I RECEIVED A CALL FROM VANDERBILT HOSPITAL AND WAS TOLD THAT THE 4 YEAR OLD WHITE MALE JUVENILE DID NOT MAKE IT.									
229									
STATUS		Active <input type="checkbox"/>		Pending <input type="checkbox"/>		Inactive <input type="checkbox"/>		Closed <input type="checkbox"/>	
Assigned To		Authority		Date		Date		Date	
NCIC/TIES Entries Have Been Made By:		Date		All Items Have Been Cleared From NCIC/TIES By:		Date		Date	

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven Dewayne Winfrey

ADDRESS: P.O.Box 303, Greenbrier Tenn 37073

PHONE NUMBER: None

NARRATIVE: On 9/23/88, Mrs Wanda Winfrey came to the sheriffs dept. There I interviewed her concearning the recent death of her son shown above. I was told by her that some of the information contained in the reports where not accurate.

"INVESTIGATIVE NOTE" The mothers name on the previous reports show the mothers name as Nancy Winfree, which is incorrect in both first name and spelling of last name. Orignal reports should reflect the name of Wanda Winfrey as the mother of the victim. Further the victims name was also incorrect in which the previous reports show the victims name as Steven C Winfree, The reports should reflect the name of Steven Dewayne Winfrey.

Further it was learned that the mother of victim is the sister of Walter Phillips. She (Wanda Winfrey) further told me that she did not have any type of insurance coverage on the victim that would pay in case of death. She (Wanda Winfrey) further signed a affidavit giving Vanderbilt Hospital permission to release all medical records concearning the victim to this agency.

(When all information is obtained and this file completed, Mrs Winfrey wishes that a complete copy of this file be mailed to her at the above adress)

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☒


CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/23/88

INVESTIGATIVE REPORT

Case No. 88-4298-261				
TN0740000	88	09	17	1737
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven C Winfree DOB/ 9/24/84

ADDRESS: Wilson Street, Greenbrier Tenn

PHONE NUMBER: None

NARRATIVE: On 9/19/88, I recieved a copy of an offense report from Det Sgt Green, the report showed that the above victim had died from an electrical shock from a fence at the Phillips residence located on dividing ridge road in Ridgeway Robertson County Tenn. A summary shown on the report by Patrol Sgt Hilliard showed that he and officer Cavender where on patrol in the area when they where flagged to stop by a subject on a three wheeler and told that a young boy had stoped breathing at the Phillips residence, according to the report they arrived at the residence to find the child unconciouse and found him not to be breathing where Deputy Cavender and a niighbor began C.P.R. on the child while Sgt Hilliard Called for further assistance. Hilliard further revealed in his report that the victims mother Nancy winfree dropped the child off at the residence earlier that day and that he and the other children where playing in the back yard area of the residence when a short while later he (Walter Phillips) noticed that the victim was not playing with the other children when he went to investigaye he found the child on the inside of the dog pen laying over the electric fence that lines the inner side of the dog pen. At that Time the child was taken into the house by family members and afterwards he was flown out to Vanderbuilt Hospital by Life Flight. Hilliards report further stated that he recieved a call

STATUS: ACTIVE ☐

PENDING ☐

INACTIVE ☐

CLOSED ☐

1/1/89
CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: from officials (unknown accordind to the report) from Vanderbuilt Hospital that told him that the child died.

.....INVESTIGATORS NOTE.....: On 9/19/88 I recieved this information as previously described, an investigator was not notified at the time of the incident therefor the following information was obtained by myself during a follow up investigation some 48 hours later.

On 9/19/88 I furter spoke with officer Cavender who also was at the scene of the incident, He could not add any further information other than it appeared that Mr Phillips or someone at the residence had possibly been cunsuming some alcoholic type beverages for there was a couple of budweiser cans setting on a table at the rear porch area where they said they where setting, Further that Mr Phillips looked according to the reddish complexion to the face to have had a few beers but did not appear to Cavender to be intoxicated. Further that he (Cavender) observed the dog pen and from his memory he told me that he belives that there where two stands of electrical fence wire around the inner side of the pen, further that one of the m was approximatly one foot from the ground, Cavender further told me e that he observed a burn or bruise mark on the leg of the child tha t appeared to have been caused by a wire or some type. He further told me that there was no other marks such as bruising or laseration s or contusions that he saw on the body of the child and that he o

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: was dressed in a pair on sneakers, short pants and shirt.
After speaking with Deputy Cavender, I drove to the location
of the incident where I observed the residence, It being a small
white frame hose having a front and rear concrete porch area, furthe
r having an add on onning type car port to the west side of the resi
dence, further having a small wooden storage shed located directly
to the rear of the back porch of the residence being approximatly
15 feet from the porch, further the before mentioned dog pen was
located to the rear of the shed attatched to the rear of the shed.
The pen was made of wooden post placed approximately 8 to 9 feet apart
having what appeared to be 36 inch by 4X4 farming fence attatched
on the outer side of the post and to the rear of the shed. The meas
urements of the pen where approximatly 36 foot deep and 42 feet in
width, measurements where stepped off being 12 steps by 14 steps.
I furter examined the described pen and was unable to locate the
electric wiring as described by Sgt Hilliard in his report or by
Deputy Cavender whom I had previously talked with. I further observe
d two chow dogs that occupy the pen. Afterwards I walked to a neigh
bors residence located due west of the residence, there I spoke with
a White male and female who told me that they where at home when the
incident occured but that they where mowing the yard and did not know
that anything had occured until the emergency vehicles had began to

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: arrive at the residence. They further told me that the entire family was at the funeral home at the time of my visit and further that since the incident that Mr Phillips had taken the electric fence down. Afterwards I went back to the residence where I obtained my camera and photographed the residence, shed and dog pen described earlier. Further a Mr Winfree, app 18 Y.O.A. arrived at the residence and was obviously grief stricken by the death of his younger brother, he took me to the rear of the residence and took out a control box that operated the electric fence and gave it to me and further told me that I was welcome to look around the residence if I wished, further that he was not at the residence the day of the incident but that his uncle (Mr Phillips) was also very upset as to what had happened. Afterwards I took the control Box to my unit where I examined it closely and further photographed it. and afterwards listed all pertinent information as follows:

Produced by: FIDO-SHOCK inc. 5360 National Drive, Knoxville Tenn, 37914. "Solid State Pet Deterent electric fence controller". Power by 110-120 Volt, 60 Hz Ac. "DANGER" Any Alterations to the designe of this charger may cause seriouse electrical shock. Further showes an intermittent output of current and showes to be used with 12 to 20 guage wire only. Model # SS-750. also below is a square silver sticker with B-6 labeled on it. The device is U/L listed No. 11N0. Serial

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

234

Page 1 of 2

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: No. G-04346. also a code No. 305-159 in the lower left corner. Also in the lower center of the device is a label listed " Use 1/16 Amp time delay fuse only " I further upon examining the two fuses contained in the device found them to be 1/4 Amp, 250 Volt No. 313 each both showing manufacturer code as L F Fuse. Both fuses being four times the strength recommended by the manufacturer.

After leaving the Phillips residence, I returned to my office where I called the Vanderbilt Emergency room to find out what the results of the autopsy that I understood that they had performed. I was told by a nurse there that they did not perform an autopsy that the body was sent to the metro medical examiners office. Afterwards I contacted the medical examiners office where I spoke with Doctor Simpkins. He further told me that he did not perform an autopsy that the body was brought to there office simply for record purposes only. He further told me that the probable cause for death was cardiac arrest due to an electrical shock. he further told me that the victim had a small burn on the left posterior wrist, also to the rear of the right knee joint. Doctor Simpkins further told me that he did not examine the victim that he recieved his information from the Vanderbilt Emergency room report and he further was unable to tell me the Doctor name who examined the victim.

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐


CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

235

INVESTIGATIVE REPORT

Case No. 88-4298-261				
TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: Afeterwards I obtained the name and phone number of the Doctor who was a Dr Brian Gibler, Phone No. 353-0327. I called Mr Gibler and after he verified my position I asked him pertinent ques tions about the victim. He told me that the child was brought into the emergency room in full cardiac arrest and that hte family told him that the child had been shocked by an electric fence. He further told me that the family was obviously grief stricken and that he did not suspect any foul play. He further told me that he could not offer any information as to the crime scen itself but that there was a burn mark on the leg of the victim and that it appeared that it could have been caused by an electrical fence. I further ask the Doctor if a small amperage such as the before mentioned control box could have caused the childs heart from beating, he then told me that he was not familiar with electricity and that it was the first case of this nature that he had seen but that all he knows is that an electrical shock can and on some occasions will stop the heart from beating. I was unable to obtain any further information from Dr Gibler. After speaking with him I prepared an authorization for medical information release form in wich I plan to have a family member signe and obtain all medical records pertaining to this case.

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐

1 Dent 50
CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven Dewayne Winfrey

ADDRESS: P.O.Box 303, Greenbrier Tenn 37073

PHONE NUMBER: None

NARRATIVE: On 9/23/88 Mrs Wanda Winfrey came to the sheriffs dept. There I interviewed her concerning the recent death of her son shown above. I was told by her that some of the information contained in the reports where not accurate.

"INVESTIGATIVE NOTE" The mothers name on the previous reports show the mothers name as Nancy Winfree, which is incorrect in both first name and spelling of last name. Original reports should reflect the name of Wanda Winfrey as the mother of the victim. Further the victims name was also incorrect in which the previous reports show the victims name as Steven C Winfree, The reports should reflect the name of Steven Dewayne Winfrey.

Further it was learned that the mother of victim is the sister of Walter Phillips. She (Wanda Winfrey) further told me that she did not have any type of insurance coverage on the victim that would pay in case of death. She (Wanda Winfrey) further signed a affidavit giving Vanderbilt Hospital permission to release all medical records concerning the victim to this agency.


(When all information is obtained and this file completed, Mrs Winfrey wishes that a complete copy of this file be mailed to her at the above adress)

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☒



CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/23/88

CPSC EXHIBIT	2	DATE	12/07/88
FIRM	IDI# 881115CCC2060		
NAME	David M. Galanti, Invest. CPSC		



N.E. corner
of Dog Compound




Inside pre-existing
Fence where victim
was found.

CPSC EXHIBIT	1	DATE	12/07/88
FIRM	IDI # 881115CCC2060		
NAME	David M. Galanti, Invest. CPSC		



ELECTRIC
CONTROLLER



68 A0117

NASHVILLE, TN.
BANNER
9/19/88

15

21 Greenbrier 4-year-old dies after shock from fence

From Banner staff reports

GREENBRIER — A 4-year-old Greenbrier boy died Saturday around 7:30 p.m. after he apparently stumbled into an electric fence and was severely shocked, according to Robertson County Sheriff's deputy Charles Hillard.

The child, Steven C. Winfree, and his sister were visiting the home of Walter Phillip of Dividing Ridge Road in Greenbrier about 23 miles north of Nashville.

Phillip told police the boy was playing with some other children about 5:30 p.m. Saturday in the backyard when he

stumbled into an electric fence inside a dog pen.

The 24-volt electric fence is used, Phillip said, to keep the dogs away from the fence surrounding the pen.

The child, the son of Steven Carl and Wanda Winfree of Maple Street, was taken by the Lifeflight helicopter to Vanderbilt University Medical Center, where he later died.

While on their way to the scene, Robertson County Emergency Medical Service workers notified Vanderbilt about the situation.

The emergency helicopter flew to the scene and landed in the neighborhood, according to

Robertson County Emergency Service Director Bob Fletcher.

"The sheriff's deputy was already on the scene so they started CPR," Fletcher said.

Winfree's body has been taken to Nashville General Hospital to be examined, Vanderbilt officials said today.

Robertson County Chief Deputy Milton Frederick said the department is still investigating the incident.

"We'll probably have a comprehensive report later today," Frederick said.

Frederick said officials are investigating to see if the fence was operating properly when the child fell on it.

EPO.7

OCT 31 1988

881115000 2060

240

ACCIDENT INVESTIGATION REQUEST FORM

Document Number 28A0117A1

Date of Incident 9/17/88 Category I.D. SECT 1519F9

Follow-up Requested ☐ Hazard Analysis ☐ Section 15 ☒

Type Follow-up Requested ☐ Telephone Call ☐ On-Site ☐

Headquarters Contact Dave Johnson 492-6608

Assignment Message Conduct an investigation of the electric fence related death reported in the attached news article. Contact local officials for information on the product, the accident scenario and the cause (malfunction of unit). Obtain a copy of any report regarding this death, including that of any analysis of the product.

Person(s) to Contact Co. Sheriff Det Charles Wilson
Robertson Co. Chris D. Doty
Milton Frederick
Greenville, TN

Guideline _____

Requested By R. Jackson

Task Number 88115CCC 2060

Assigned to Chi Date 11/15/88

To: Division of Corrective Actions, Attn: Marc J. Schoen

From: CENTRAL Regional Center

Subject: Section 15 Field Investigation Status

FC890040

File Number : ~~FC890040~~ Date Opened: 89/03/06 Date Closed: 1/1/

CACA Contact: ~~DOUGLAS~~ RO: ~~LEE~~ FOCR T Rogers / L.G. GAYMAN

Company Name: F1 - SHOCK, Inc.

Street : 5360 NATIONAL DRIVE

City : KNOXVILLE State: TN Zip: 37914

Co. Contact : Phone - - -

Type : MEg X Dist Retail Prv Labeler Importer

NEISS PRODUCT CODE: 0605

Product Description: SOLID STATE PET DETERRENT

ELECTRIC FENCE ~~SHOCK~~ CONTROLLER

Model : #SS-750

Brand : FIDO - SHOCK

Potential Hazard: Electrocution

IDI: 881115CCC2060

Sample: 1

Comments:

Location: Accession: Box:

* * * * *

REGIONAL CENTER PLANS FOR FOLLOW-UP

PRIORITY: A B C D (Circle)

Pot. Timeliness: yes no

TIMETABLE

3/6/89 Data Dump Requested / / Kick-Off Meeting

 / / Establishment Inspection

 / / PSA Submitted / / PSA Response

 / / PSA Submitted / / PSA Response

 / / Other Investigation IDI's Samples

 / / Establishment Inspection

 / / Preliminary Determination To Be Submitted

[Form 1b - field input (REVISED 1/88)]

*Just what I needed
Data Dump*

23 MAR 1989

YMAN

CONSUMER PRODUCT SAFETY COMMISSION
ROUTE SLIP

TO

Keith

Take necessary action ☐

Approval or signature ☐

Comment ☐

Prepare reply ☐

Discuss with me ☐

For your information ☐

See remarks below ☐

FROM

Cathy

DATE *2/10/89*

REMARKS

This report says that the owner of the Fido-shock had to use larger fuses to get the product to work. Should this be the case?

Cathy:

ES would like to test product

HA.

CPSC FORM 108 9/73

*into back
Data Dump*

243

23 MAR 1989

To: Division of Corrective Actions, Attn: Marc J. Schoen

From: CENTRAL Regional Center

Subject: Section 15 Field Investigation Status

FC890040

File Number : ~~FC890040~~ Date Opened: 89/03/06 Date Closed: 1/1

CACA Contact: C. DOWNS RO: FOCR T Rogers / L.G. GAYMAN

Company Name: F1 - SHOCK, Inc.

Street : 5360 NATIONAL DRIVE

City : KNOXVILLE State: TN zip: 37914

Co. Contact : _____ Phone _____

Type : MEg X Dist _____ Retail _____ Prv Labeler _____ Importer _____

NEISS, PRODUCT CODE: 0605

Product Description: SOLID STATE PET DETERRENT

ELECTRIC FENCE ~~SHOCK~~ CONTROLLER

Model : #SS-750

Brand : FIDO - SHOCK

Potential Hazard: Electrocution

IDI: 881115CCC20601

Sample: _____

Comments: _____

Location: _____ Accession: _____ Box: *

* * * * *

REGIONAL CENTER PLANS FOR FOLLOW-UP

PRIORITY: A B C D (Circle)

Pot. Timeliness: _____ yes _____ no

TIMETABLE

3/6/89 Data Dump Requested 1/1 Kick-Off Meeting

1/1 Establishment Inspection

1/1 PSA Submitted 1/1 PSA Response

1/1 PSA Submitted 1/1 PSA Response

1/1 Other Investigation _____ IDI's _____ Samples

1/1 Establishment Inspection

1/1 Preliminary Determination To Be Submitted

[Form 1b - Field input (REVISED 1/88)]

① Starting - shock
② Data Dump

244

~~RESTRICTED~~

3/16/89

245

PRODUCT SAFETY AGREEMENT (PSA) TECHNICAL EVALUATION REQUEST
Notes: Print, use black pen, no blue ink.

Requested by: Logan/Logan Org. Code: CH Reg. Off.: C
Date: 3-16-89 Priority: a b c d

A B C D
IUF
MFG
CAG
FNI EC890040

PRODUCT INFORMATION

Manufacturer: FI SHOCK City/State: Knoxville TN Zip: _____
Product (generic name): electric pet fence
Brand name, model, etc.: 7105 Shock
Sample number: _____

EVALUATION REQUESTED:

Data Review

881115 CAG 2060/0605

Item: Shock
(describe hazard)

Requested date: 3/25/89

Attachment: _____

NOTES:

PSA ACTION (FOR PSA USE ONLY)

Request number: 4226

Compliance no.: EC890040

Priority: 6

Received: 3/16/89

Received by: B. G. G. G.

Date Requested: 3/16/89

Due Date: 3/16/89

Item: FI Shock

Product: electric pet fence

Req'd. by: DOCKERS

ASSIGNMENT:

Date: 3/16 Org: EP

Assigned to: EDWARDS

Req. Summary: DATA REVIEW

Completed: _____

To G. Gayman

DIRECTORATE FOR EPIDEMIOLOGY

DATA REVIEW

RESTRICTED

TO : T. Rogers, CACA *aut*
 Thru: F. Brauer/C. Perez
 FROM : M. Edmonds, EPHA 6H

DATE: 3/23/89
 DATE DUE: 3/25/89
 PRIORITY: "5"

REQUEST: PSA 4226, F1 Shock, Electric Pet Fence

Fido Shock

HAZARD PATTERN: Shock

SELECTION CRITERIA:

Product Code(s): 0605, 1715, 1871, 4062
 Text/Other : F1 Sh, Fisho, Fido
 Time Frame : 840000 - 890320
 NFIRS Search Criteria: N/A

INCIDENTS IDENTIFIED:

<u>Data Base(s)*</u>	<u># of Incidents</u>	<u># of Deaths</u>
Accident Investigations	<u>1</u>	<u>1</u>
Reported Incidents	<u>-</u>	<u>-</u>
Death Certificate File	<u>-</u>	<u>-</u>
NEISS (Actual number)	<u>-</u>	<u>-</u>
NFIRS	<u>-</u>	<u>-</u>
TOTAL	<u>-</u>	<u>-</u>

* Incidents reported in more than one data base are included only once, in the data base listed first. These are reports EPFA was able to identify from the CPSC data files and should not be considered a statistical sample or a complete count of all such incidents that may have occurred.

NOTES/COMMENTS:

The printout is attached.

3/14
C/S
C/S

To: Division of Corrective Actions, Attn: Marc J. Schoen
From: CENTRAL Regional Center
Subject: Section 15 Field Investigation Status

File Number : FC 89-400 Date Opened: 89/03/06 Date Closed: 1/1/

CACA Contact: C. Downs RO: LGG

Company Name: FI - SHOCK, Inc.

Street : 5360 NATIONAL DRIVE

City : KNOXVILLE State: TN Zip: 37914

Co. Contact : _____ Phone _____

Type : MFg ☒ Dist _____ Retail _____ Prv Labeler _____ Importer _____

NEISS PRODUCT CODE: 0605

Product Description: SOLID STATE PET DETERRENT
ELECTRIC FENCE ~~CONTROL~~ CONTROLLER

Model : #SS-750

Brand : FIDO - SHOCK

Potential Hazard: Electrocution

IDI: 881115CCC2060

Sample: _____

Comments: _____

Location: _____ Accession: _____ Box: _____

* * * * *

REGIONAL CENTER PLANS FOR FOLLOW-UP

PRIORITY: A B C D (Circle)

Pot. Timeliness: _____ yes _____ no

TIMETABLE

3/6/89 Data Dump Requested 1/1/ Kick-Off Meeting

1/1/ Establishment Inspection

1/1/ PSA Submitted 1/1/ PSA Response

1/1/ PSA Submitted 1/1/ PSA Response

1/1/ Other Investigation _____ IDI's _____ Samples

1/1/ Establishment Inspection

1/1/ Preliminary Determination To Be Submitted

[Form 1b - field input (REVISED 1/88)]

247



PRODUCT SAFETY ASSESSMENT (PSA) TECHNICAL EVALUATION REQUEST
Please Print, use black pen, no blue ink.

Requested by: L. George / Clayton Reg. Off.: FOR
Date: 3/6/89 Priority: a b b c d Org. Code: ATZ

PRODUCT INFORMATION
Manufacturer: Fi-Shock, Inc. ID# FC89-40
City/State: Knoxville TN. ZIP: 37914
Product (generic name): PET DETERGENT
Brand name, model, etc.: ELECTRIC FENCE CONTROLLER
Sample numbers: #SS-750

EVALUATION REQUESTED:
Please do Data Dump on the
above product.

Hazard: Electrocution HAZARD
(describe hazard)
Requested date: 4/1/89 Attachment: FPE 891115

NOTES:

PSA ACTION (FOR PSA USE ONLY)
Request number: 1
Compliance no.: 1
Priority: 1
Received: 1
Received by: (time/date)
Date Requested: 1
Due Date: 1
Y/C: 1
Product: 1
Req'd. by: 1 Org: 1
ASSIGNMENT:
Date: 1 Org: 1
Assigned to: 1
Req. Summary: 1
Completed: 1

1/89

FIELD ACTIVITY COVERSHEET

1. REGION/STATE FOCR/ATL-SO		2. OPERATION (Check One) <input type="checkbox"/> Inspection <input type="checkbox"/> Establishment Visit <input type="checkbox"/> Telephone Contact <input checked="" type="checkbox"/> Investigation <input type="checkbox"/> Other _____		3. DATE 12/01/88	
				4. NUMBER (For FO Use) 88115CCC2060 88115CCC2060	
5. ESTABLISHMENT Name <u>Fi-SHOCK, Inc.</u> Address <u>5360 National Drive</u> City <u>Knoxville</u> State <u>TN</u> Zip <u>37014</u> Telephone No. <u>(615) 526-7224</u>					
6. RELATED FIRM <input type="checkbox"/> Parent <input type="checkbox"/> Headquarters <input type="checkbox"/> Subsidiary <input type="checkbox"/> Other Name _____ City _____ State _____					
7. PRODUCTS COVERED <u>FIDO SHOCK Pet Deterrent</u>			8. OTHER CONSUMER PRODUCTS <u>N/A</u>		
9. ESTABLISHMENT TYPE N/A <input type="checkbox"/> Manufacturer <input type="checkbox"/> Importer <input type="checkbox"/> Wholesaler <input type="checkbox"/> Own Label Distributor <input type="checkbox"/> Retailer <input type="checkbox"/> Repackager <input type="checkbox"/> Other _____			10. ANNUAL PRODUCTION N/A Products Covered \$ _____ Units _____ Other Products \$ _____ Units _____		
11. I.S. BUSINESS N/A % Received _____ % Shipped _____		12. SAMPLES COLLECTED - None		13. MIS CODE 32626	
14. HOURS Activity <u>14</u> Travel <u>4</u>					
15. REASON FOR ACTIVITY (Assignment Reference) In Depth Investigation #88115CCC2060					
16. EMPLOYEE'S NAME David M. Galanti		TITLE PSI		SIGNATURE <i>David M. Galanti</i>	
17. <input checked="" type="checkbox"/> ENDORSEMENT <input type="checkbox"/> REMARKS <input type="checkbox"/> SUMMARY <input type="checkbox"/> OTHER <p>A 4 year old boy was electrocuted when he fell across an electric "Pet Deterrent" fence. There were no witnesses to the incident. The victim's adult relatives found the victim after they had missed him from playing for a few minutes.</p> <p>The victim's uncle installed the electrically charged fence. When the uncle was putting the fence up he found that the recommended 1/16 amp fuses would blow each time power was supplied to the control box. The victim's uncle inserted 2-1/4 amp fuses into the control box and the fence worked. The victim's aunt stated that the only way to get the fence to work was to use stronger fuses than those recommended.</p> <p>The electric fence had been discarded at the time of the investigation. The investigator was unable to obtain the control box as a sample and for examination due to possible future litigation. F/U: An inspection of the manufacturer will be assigned.</p>					
18. REVIEWER'S NAME George L. Lester		TITLE SPSI		SIGNATURE <i>George L. Lester</i>	
19. REVIEW DATE 1/25/89		DISTRIBUTION 0: EPDS, cc: FOCR Inv file, ATL (LGG), CACA, cc: LGG, GLL, RF			

1. CASE NO. 881115CCC2060			2. INVESTIGATOR'S ID 8 9 3 5			3. OFFICE CODE 8 3 8			EPIDEMIOLOGIC INVESTIGATION REPORT
4. DATE OF ACCIDENT YR MO DAY 8 8 0 9 1 7			5. DATE INVESTIGATION INITIATED YR MO DAY 8 8 1 2 0 6						
6. SYNOPSIS OF ACCIDENT OR COMPLAINT <u>A four year old male victim died of Cardiac/Respiratory arrest after receiving an electric shock by falling across a electric dog fence. The victim was playing "frisby" with his cousin and was attempting to retrieve the toy which had inadvertently gone over the fence. Examination of the controller for the electric dog fence identified two fuses which were four times the strength recommended for use by the manufacturer.</u>									
7. LOCATION (Home, school, etc.) Home - Back Yard 1 1				8. CITY Ridge Top			9. STATE Tennessee T N		
10A. FIRST PRODUCT Electric Wire 0 6 0 5				11A. TRADE/BRAND NAME, MODEL NUMBER, MANUFACTURER & ADDRESS "FIDO-SHOCK", Model #SS-750 FI-Shock Inc., 5360 National Drive, Knoxville, TN					
10B. SECOND PRODUCT None				11B. TRADE/BRAND NAME, MODEL NUMBER, MANUFACTURER & ADDRESS N/A					
12. AGE OF VICTIM 0 0 4		13. SEX (Use numerical code) MALE - 1 FEMALE - 2 UNKNOWN - 3 1		14. DISPOSITION Fatality 8			15. INJURY DIAGNOSIS Electric Shock 6 7		
16. BODY PART All Parts 8 5		17. RESPONDENT(S) (Mother, Friend) Police Detective 3		18. TYPE INVESTIGATION ON SITE 1 TELEPHONE 2 OTHER 3 1		19. TIME SPENT 1 4 0			
20. ATTACHMENTS Multiple 9		21. CASE SOURCE Newspaper 0 5		22. REVIEWED BY YR MO DAY 8 2 9 8 8 9 0 1 2 5					
23. PERMISSION TO DISCLOSE NAMES (NON-NEISS CASES ONLY) CPSC MAY DISCLOSE MY NAME <input type="checkbox"/> CPSC MAY NOT DISCLOSE MY NAME <input checked="" type="checkbox"/> X									
24. NARRATIVE (See instructions on Other Side)						25. REGIONAL OFFICE DIRECTOR REVIEW DATE			

(USE OTHER SIDE AND ADDITIONAL SHEETS IF NECESSARY)

881115CCC2060

Pre-Accident:

This investigation was conducted in response to a newspaper report that a four year old male child died as a result of injuries received after he fell across a electric dog fence. Information gained in this case was obtained through an on-scene examination of the accident area, and conversations with the victim's aunt and police officials.

Victim's aunt stated that her husband purchased the entire electric dog fence system approximately one year ago at Lowe's Building and Supply, Clarksville, Tennessee. The electric fence was installed by victim's uncle inside of a existing dog compound that measured approximately 36 feet by 42 feet. The purpose of the electric fence was to prevent two Chow dogs from jumping up on the inside of the pre-existing fence and climbing out of their enclosure. The electric dog fence consisted of two strands of electrical fence wire attached to wooden stakes approximately one foot from the inside of the pre-existing fence. The bottom wire of the electric fence was approximately one foot from the ground and the top wire was approximately three feet from the ground.

Victim's aunt stated that the victim was approximately four feet tall and weighed approximately fifty pounds. Victim had brown hair and brown eyes. Victim was a very active child and had a history of bronchitis. Victim's mother brought the victim to their house in order for him to play with his cousin. Victim was wearing tennis shoes, a pull-over "T" shirt and short pants at the time of the accident. Victim's mother was not present at the time of the accident.

At approximately 5:15 pm, September 17, 1988, victim was playing "Frisby" with his three year old cousin in the back yard. Weather conditions were cloudy and overcast, and the temperature was approximately 75 degrees fahrenheit. It had rained earlier in the day and the ground was still wet.

Accident:

At approximately 5:30 pm, victim's uncle, who was sitting on his back porch, noticed that the victim was no longer in sight. Victim was discovered by his uncle inside of the dog compound slumped across the electric dog fence, but not in contact with the outside pre-existing fence. Victim was unconscious and a burn mark was observed behind his right knee.

881115CCC2060

Post Accident:

Victim's uncle immediately picked up victim (without being shocked) and carried him into the house. A county police patrol responded to the location and attempted to revive the victim by Cardio Pulmonary Resuscitation (CPR). Victim was subsequently transported to Vanderbilt Hospital, Nashville, Tennessee where he was pronounced dead. Cause of death, as reported by the medical examiner, was identified as cardio/respiratory arrest due to electric shock and the manner of death identified as accidental.

Victim's uncle subsequently removed both strands of the electric dog fence and threw them away, however, the electrical control box was not discarded and was taken by county police detectives for examination. Their examination revealed the existence of two fuses, 1/2 Amp, 250 Volts each, inserted in the control box. It was observed from the labeling on the control box panel that both of the fuses that were used in the control box were four times the strength recommended by the manufacturer. Victim's aunt stated that when her husband was putting up the fence he attempted to use the fuses that came with the electric fence system, however, each time the recommended fuses were used the fuses would "blow" as soon as power was supplied to the control box. Victim's aunt stated that the only way to get the fence to work was to use stronger fuses.

A request was made by the CPSC investigator to obtain the control box for a sample and examination however, due to possible future litigation, the request was refused.

Telephonic contact with Lowe's Building and Supply, Clarksville, Tennessee revealed that they no longer had the Fido-Shock, pet deterrent in stock, and they have not experienced any product complaints

Standards:

No voluntary or mandatory standards information was observed on the product.

Product Identification:

The product is an electrical control box enclosed in black plastic and generally mounted indoors, on the walls of a building. Product is manufactured by Fi-SHOCK, Inc., 5360 National Drive, Knoxville, Tennessee, 37914. Additional labeling states: FIDO-SHOCK, Solid State Pet Deterrent, Electric Fence Controller. The controller is powered by 110-120 Volt 60Hz ac. Additional warnings include: "DANGER" any alterations to the design of this charger may cause serious electrical shock. At top center of the box a warning states "use one sixteenth Amp time delay fuses only"

No assembly instructions or additional warnings information was available.

252

881115CCC2060

Attachments:

1. Photographs
2. Medical Examiners Investigative Report, dtd 9/18/88
3. Robertson County Offense Report, dtd 9/17/88
4. Investigation Report, dtd 9/19/88
5. Newspaper Article, 9/19/88 (Nashville Banner)
6. Copy of CPSC Assignment

253

CPSC EXHIBIT 1 DATE 12/07/88
FIRM IDI # 881115CCC2060

NAME David M. Galanti, Invest. CPSC



ELECTRIC
CONTROLLER




CPSC EXHIBIT 2 DATE 12/07/88
FIRM IDI# 881115CCC2060

NAME David M. Galanti, Invest. CPSC



N.E. Corner of
dog Compound



Inside pre-existing
Fence where victim
was found.

METROPOLITAN NASHVILLE
AND DAVIDSON COUNTY
OFFICE OF THE MEDICAL EXAMINER
FORENSIC SCIENCES CENTER
84 HERMITAGE AVENUE
NASHVILLE TN 37210-2110
(615) 259-6920


CASE NO. MEC 88-1666

REPORT OF INVESTIGATION BY COUNTY MEDICAL EXAMINER

DECEASED Steven Winfree RACE: W SEX: M AGE: 3
First name Middle name Last name
HOME ADDRESS P O Box 303 Greenbriar Tn M W S D OCCUPATION:
Number and Street City or County State
TYPE OF DEATH: Violent ☐ Casualty ☒ Suicide ☐ Suddenly when in apparent health ☐ Found Dead ☐
(Check one only) In Prison ☐ Suspicious, unusual or unnatural ☐ Cremation ☐
Comment electric shock
If Motor Vehicle Accident Check One: Driver ☐ Passenger ☐ Pedestrian ☐ Unknown ☐
Notification by Dr. Ann Byers / Vandy ER 322-0145 Address Nashville
Investigating Agency M.P.D.

DESCRIPTION OF BODY: Clothed ☐ Unclothed ☒ Partly Clothed ☐ Circumcised Yes ☐ No ☐
Eyes Brown Hair Brown Mustache Beard
Weight 38.6 Pounds Length 40 Inches Body Temp. Fahrenheit Date and Time 9/17/88
Rigor: Yes ☒ No ☐ Lysed ☐ Livor Color Fixed ☐ Non-Fixed ☐

Marks and Wounds Cyanosis



PROBABLE CAUSE OF DEATH	MANNER OF DEATH	DISPOSITION OF CASE
<u>Cordis. Rep. Arret. due to Electric Shock from Dog Fence.</u>	(Check one only) Accident <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Suicide <input type="checkbox"/> Unknown <input type="checkbox"/> Homicide <input type="checkbox"/> Pending <input type="checkbox"/>	1. Not a medical examiner case <input type="checkbox"/> 2. Autopsy requested Yes <input type="checkbox"/> No <input type="checkbox"/> Autopsy ordered Yes <input type="checkbox"/> No <input type="checkbox"/> Pathologist <u></u>

I hereby declare that after receiving notice of the death described herein I took charge of the body and made inquiries regarding the cause of death in accordance with Section 38-701-38-714 Tennessee Code Annotated; and that the information contained herein regarding such death is true and correct to the best of my knowledge and belief.

Date 9-18-88 County of Appointment Davidson Signature of County Medical Examiner Dr. P. J. Simpson MD 256

PERSONAL HISTORY: Suicide attempts ☒ Suicide threats ☐ Hobbies, aptitude & skills with firearms, chemicals, etc. Domestic, premarital or marital conflicts ☐ Financial or business reverses ☐ Social or religious conflicts ☐ Legal difficulties ☐ Criminal record ☐ Unemployment ☐ Fear of disease ☐ Other (specify) _____

CONDUCT BEFORE DEATH: Efforts to prevent help ☐ Efforts to obtain help ☐ Suicide attempt: Admitted ☐ Denied ☐ Refusal to talk ☐ Written declaration of intended suicide ☐ Accusations against others ☐ Other (specify) _____

	LAST SEEN ALIVE	INJURY OR ILLNESS	DEATH	DISCOVERY	MEDICAL EXAMINER NOTIFIED	VIEW OF BODY	POLICE NOTIFIED
DATE	9-17-88	9/17/88	9-17-88		9-17-88	9-17-88	<i>Same</i>
TIME	1700	± 1700	1904		1925	1300	
	LOCATION		CITY OR COUNTY		TYPE OF PREMISES (HOSPITAL, HOTEL, HIGHWAY, ETC.)		
INJURY OR ONSET OF ILLNESS	<i>Davidson Ridge Rd. Robertson County</i>				<i>Residence</i>		
DEATH	Vanderbuilt ER		Davidson		Hospital		
VIEWING OF BODY BY MEDICAL EXAMINER	F S C		Davidson		County Morque		

MEDICAL ATTENTION AND HOSPITAL OR INSTITUTIONAL CARE			
NAME OF PHYSICIAN OR INSTITUTION	ADDRESS	DIAGNOSIS	DATE

CIRCUMSTANCES OF DEATH		
	NAME	ADDRESS
FOUND DEAD BY		
LAST SEEN ALIVE BY		
WITNESS TO INJURY OR ILLNESS AND DEATH		
N O K FH	(Mother- Wanda Winfree) Cole & Garrett	865-6164

NARRATIVE SUMMARY OF CIRCUMSTANCES SURROUNDING DEATH:

HX- A three year old baby was life flown from Greenbriar Tenn to V U M C. The patient had an electrical shock received from a vent. He was coded for approximately 40 minutes then died. The baby was born at Vanderbuilt and has been there several times for various reason but has no personal Doctor.

@ P.R. & therapy, no response began in 2 R U out 1825.

Continued demanding 1901 (see Card record on this sheet)

Electrical Burn small area. Left foot wrist area. & large larger Burn area behind at knee joint on leg. response to therapy Negative. *no other evidence of trauma.*

Cardio Respiratory Arrest () due to Electric fence shock.

(Blood drawn for toxicology.) No urine available
Happen at Davidson Ridge Rd. Robertson County - toxicologic

OFFENSE REPORT

1. Offense INFORMATION		2. Classification ACCIDENTAL DEATH		TN 0740010		3. Date 09-17-88		4. Time 1737	
3. Location of Incident DIVIDERIDGE RD LAST RES. UN D-WALKER				4. Zone 2		5. Date/Time Occurred 09-17-88 1737		6. Date/Time Police Arrived 09-17-88 1737	
7. Victim STEVEN C. WINEREE		Sex M	Race N/A	D.O.B. N/A	8. Home Address WILSON ST. GREENSBORO, NC		9. Phone 		
10. Business Address N/A		11. Business Phone N/A		12. Person Arrested N/A		Sex 	Race 	D.O.B. 	
13. Complainant WALTER PHILLIP		Sex 	Race 	D.O.B. 	14. Home Address RT #3 BOX 301 GOODLETTSVILLE		15. Phone 		
16. Witness' Name 		Sex 	Race 	D.O.B. 	17. Home Address 		18. Phone 		
19. VEHICLE NONE		a. License No. (LIC) 	b. State 	c. Year 	d. Type 	e. Vehicle Identification No. (VIN) 		f. Year 	g. Make
h. Model 		i. Other Description or Damage 							
20. WEAPON 		Gen. Description 		Serial # (SN) 14/14		Make 		Caliber 	
21. PROPERTY 		Description 		Serial # (SN) N/A		Unit 		22. Total Value 	
23. Reporting Officer HILLARD, CHARLES		Badge 4366T		Unit 530		24. Approving Supervisor 			
25. NARRATIVE: Give All Information Necessary, Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witnesses' Names, Sex, Race, D.O.B., Addresses And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.									
<p>ON SEPT. 17-88 AT 5:37 PM. WHILE ON DIVIDERIDGE ROAD A SUBJECT FLAGGED ME DOWN AND STATED THAT THERE'S A BOY THAT'S DOWN AND HAS STOP BREATHING. AT THIS TIME MYSELF AND OFFICER BANCY CAUENDER WENT INSIDE THE RESIDENT AND FOUND A WHITE MALE JUVENILE IN THE FLOOR WITH SEVERAL SUBJECTS WERE AROUND THE KID. AT THIS TIME A NEIGHBOR STATED THAT THE YOUNG BOY GOT INTO AN ELECTRIC FENCE THAT WAS INSIDE THE DOG PEN. OFFICE CAUENDER AND ANOTHER SUBJECT IDENTIFIED AS PAMI OLAN STARTED C.P.R. ON THE SUBJECT WHILE I DISPATCHED THE AMBULANCE SERVICE, RIDGETOP FIRE DEPT., AND VANDERBILT'S LIFE-FLIGHT TO THE SCENE. APPROX 15 MIN LATER THE AMBULANCE ARRIVED AND TOOK OVER C.P.R. UNTIL LIFE FLIGHT ARRIVED. JUST A SHORT TIME AFTER LIFE FLIGHT WAS IN ROUTE TO VANDERBILT HOSPITAL WITH THE SUBJECT.</p> <p>THE OWNER OF THE RESIDENT STATED THAT THE MOTHER OF THE 4 YEAR OLD BOY, NANCY WINEREE LEFT THE CHILD AT HIS RESIDENT WHILE SHE WENT BACK HOME. MR. PHILLIP STATED THAT THE KIDS WERE OUTSIDE PLAYING AND THEY NOTICED THAT THEY DID NOT SEE STEVEN (THE VICTIM) PLAYING WITH THE OTHER KIDS. THEY GOT UP AND LOOKED OUT AND SAW STEVEN LYING OVER INSIDE THE DOG PEN OVER THE ELECTRIC FENCE.</p>									
END OF PAGE ONE									
STATUS		Active <input type="checkbox"/> Pending <input type="checkbox"/> Inactive <input type="checkbox"/> Closed <input type="checkbox"/>		Assigned To		Authority		Date	
NCIC/TIES Entries Have Been Made By:		Date		All Items Have Been Cleared From NCIC/TIES By:		Date			

PAGE 1-OF 1

OFFENSE REPORT

PAGE 2 - OF 1

1. Offense INFORMATION		2. Classification IDENTIAL DEATH		TM 0741	38 09	17 1737																
3. Location of Incident PAGE 1 OF 1				4. Zone 2	5. Date/Time Occurred 09-07-88	6. Date/Time Police Arrived 09-17-88																
7. Victim PAGE 1 OF 1	Sex	Race	D.O.B.	8. Home Address		9. Phone																
10. Business Address		11. Business Phone		12. Person Arrested		Sex Race D.O.B.																
13. Complainant		Sex	Race	D.O.B.	14. Home Address																	
15. Phone		16. Home Address		17. Home Address		18. Phone																
19. VEHICLE		a. License No. (LIC)	b. State	c. Year	d. Type	e. Vehicle Identification No. (VIN)																
f. Year		g. Make		h. Model																		
i. Style		j. Color		k. Other Description or Damage																		
20. WEAPON	Gen. Description		Serial # (SN)	Make	Caliber	Type																
21. PROPERTY	Description					22. Total Value																
23. Reporting Officer WILLARD, CHARLES			Badge 567	Unit 540	24. Approving Supervisor																	
25. NARRATIVE: Give All Information Necessary, Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witnesses' Names, Sex, Race, D.O.B., Addresses And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.																						
<p>MR PHILLIP RAY PUT BACK ROT THE BUX AND BROUGHT HIM INSIDE THE RESIDENT JUST AS WE PULLED INTO THE DRIVEWAY. MR. PHILLIP AND I WENT OUT TO THE DOG PEN TO LOOK AT THE FENCE AND HE STATED THAT THE FENCE WAS 24 VOLT ELECTRIC FENCE THAT WAS PUT INSIDE THE DOG PEN TO KEEP THE DOGS AWAY FROM THE MAIN FENCE. THE MAIN FENCE STANDS ABOUT 3 1/2 FT. WITH THE ELECTRIC FENCE ABOUT A FOOT FROM THE GROUND ON THE INSIDE.</p> <p>THE MOTHER, NANCY WINEREE WAS INJURED AND WAS TRANSPORTED TO VANDERBILT HOSPITAL BY HER BROTHER. DOBS WINEREE'S DAUGHTER WAS AT THE RESIDENT AT THE TIME WITH MR. AND MRS. PHILLIPS.</p> <p>MYSELF AND DEP. LAWENDER LEFT THE SC. AT 6:32 P.M. AND AT 7:19 I RECEIVED A CALL FROM VANDERBILT HOSPITAL AND WAS TOLD THAT THE 4 YEAR OLD WHITE MALE JUVENILE DID NOT MAKE IT.</p>																						
<table border="1"> <tr> <td>STATUS</td> <td>Active <input type="checkbox"/></td> <td>Pending <input type="checkbox"/></td> <td>Inactive <input type="checkbox"/></td> <td>Closed <input type="checkbox"/></td> <td>Assigned To</td> <td>Authority</td> <td>Date</td> </tr> <tr> <td colspan="4">NCIC/TIES Entries Have Been Made By:</td> <td>Date</td> <td colspan="2">All Items Have Been Cleared From NCIC/TIES By:</td> <td>Date</td> </tr> </table>							STATUS	Active <input type="checkbox"/>	Pending <input type="checkbox"/>	Inactive <input type="checkbox"/>	Closed <input type="checkbox"/>	Assigned To	Authority	Date	NCIC/TIES Entries Have Been Made By:				Date	All Items Have Been Cleared From NCIC/TIES By:		Date
STATUS	Active <input type="checkbox"/>	Pending <input type="checkbox"/>	Inactive <input type="checkbox"/>	Closed <input type="checkbox"/>	Assigned To	Authority	Date															
NCIC/TIES Entries Have Been Made By:				Date	All Items Have Been Cleared From NCIC/TIES By:		Date															

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven Dewayne Winfrey

ADDRESS: P.O. Box 303, Greenbrier Tenn 37073

PHONE NUMBER: None

NARRATIVE: On 9/23/88, Mrs Wanda Winfrey came to the sheriffs dept. There I interviewed her concerning the recent death of her son shown above. I was told by her that some of the information contained in the reports where not accurate.

"INVESTIGATIVE NOTE" The mothers name on the previous reports show the mothers name as Nancy Winfree, which is incorrect in both first name and spelling of last name. Original reports should reflect the name of Wanda Winfrey as the mother of the victim. Further the victims name was also incorrect in which the previous reports show the victims name as Steven C Winfree, The reports should reflect the name of Steven Dewayne Winfrey.

Further it was learned that the mother of victim is the sister of Walter Phillips, She (Wanda Winfrey) further told me that she did not have any type of insurance coverage on the victim that would pay in case of death, She (Wanda Winfrey) further signed a affidavit giving Vanderbilt Hospital permission to release all medical records concerning the victim to this agency.

(When all information is obtained and this file completed, Mrs Winfrey wishes that a complete copy of this file be mailed to her at the above adress)

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☒


CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/23/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000	88	09	17	1737
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / Accidental

DATE & TIME OCCURED: 9/17/88 @ 1737

VICTIM: Steven C Winfree DOB/ 9/24/84

ADDRESS: Wilson Street, Greenbrier Tenn

PHONE NUMBER: None

NARRATIVE: On 9/19/88, I recieved a copy of an offense report from Det Sgt Green, the report showed that the above victim had died from an electrical shock from a fence at the Phillips residence located on dividing ridge road in Ridgetop Robertson County Tenn. A summary shown on the report by Patrol Sgt Hilliard showed that he and officer Cavender where on patrol in the area when they where flagged to stop by a subject on a three wheeler and told that a young boy had stoped breathing at the Phillips residence, according to the report they arrived at the residence to find the child unconcious and found him not to be breathing where Deputy Cavender and a niighbor began C.P.R. on the child while Sgt Hilliard Called for further assistance. Hilliard further revealed in his report that the victims mother Nancy winfree droped the child off at the residence earlier that day and that he and the other children where playing in the back yard area of the residence when a short while later he (Walter Phillips) noticed that the victim was not playing with the other children when he went to investigaye he found the child on the inside of the dog pen laying over the electric fence that lines the inner side of the dog pen. At that Time the child was taken into the house by family members and afterwards he was flown out to Vanderbuilt Hospital by Life Flight. Hilliards report further stated that he recieved a call

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐


CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: from officials (unknown accordind to the report) from
Vanderbilt Hospital that told him that the child died.

..... INVESTIGATORS NOTE: On 9/19/88 I recieved this information
as previously described, an investigator was not notified at the time
of the incident therefor the following information was obtained by
myself during a follow up investigation some 48 hours later.

On 9/19/88 I furter spoke with officer Cavender who also
was at the scene of the incident, he could not add any further imfor
mation other than it appeared that Mr Phillips or someone at the res
idence had possibly been cunsuming some alcoholic type heverages for
there was a couple of budweiser cans setting on a table at the rear
porch area where they said they where setting, Further that Mr Phill
ips looked according to the reddish complexion to the face to have
had a few beers but did not appear to Cavender to be intoxicated.
Further that he (Cavender) observed the dog pen and from his memory
he told me that he belives that there where two stands of electrical
fence wire around the inner side of the pen, further that one of the
m was approximatly one foot from the ground, Cavender further told m
e that he observed a burn or bruise mark on the leg of the child tha
t appeared to have been caused by a wire or some type. He further
told me that there was no other marks such as bruising or lase ration
s or contusions that he saw on the body of the child and that he

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐

CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No. 88-4298-261				
TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: was dressed in a pair on sneakers, short pants and shirt.
After speaking with Deputy Cavender, I drove to the location
of the incident where I observed the residence, It being a small
white frame hose having a front and rear concrete porch area, furthe
r having an add on onning type car port to the west side of the resi
dence, further having a small wooden storage shed located directly
to the rear of the back porch of the residence being approximatly
15 feet from the porch, further the before mentioned dog pen was
located to the rear of the shed attatched to the rear of the shed.
The pen was made of wooden post placed approximately 8 to 9 feet apart
having what appeared to be 36 inch by 4X4 farming fence attatched
on the outer side of the post and to the rear of the shed. The meas
urements of the pen where approximatly 36 foot deep and 42 feet in
width, measurements where stepped off being 12 steps by 14 steps.
I furter examined the described pen and was unable to locate the
electric wireing as described by Sgt Hilliard in his report or by
Deputy Cavender whom I had previously talked with. I further observe
d two chow dogs that occupy the pen. Afterwards I walked to a neigh
bors residence located due west of the residence, there I spoke with
a White male and female who told me that they where at home when the
incident occured but that they where mowing the yard and did not know
that anything had occured until the emergency vehicles had began to

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐

CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

INVESTIGATIVE REPORT

Case No.88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE:

DATE & TIME OCCURED:

VICTIM:

ADDRESS:

PHONE NUMBER:

NARRATIVE: No. G-04346. also a code No. 305-159 in the lower left corner. Also in the lower center of the device is a label listed "Use 1/16 Amp time delay fuse only " I further upon examining the two fuses contained in the device found them to be 1/4 Amp, 250 Volt No. 313 each both showing manufacturer code as L F Fuse. Both fuses being four times the strength recommended by the manufacturer. After leaving the Phillips residence, I returned to my office where I called the Vanderbuilt Emergency room to find out what the results of the autopsy that I understood that they had performed. I was told by a nurse there that they did not perform an autopsy that the body was sent to the metro medical examiners office. Afterwards I contacted the medical examiners office where I spoke with Doctor Simpkins. He further told me that he did not perform an autopsy that the body was brought to there office simply for record purposes only. He further told me that the probable cause for death was cardiac arrest due to an electrical shock. he further told me that the victim had a small burn on the left posterior wrist, also to the rear of the right knee joint. Doctor Simpkins further told me that he did not examine the victim that he recieved his information from the Vanderbuilt Emergency room report and he further was unable to tell me the Doctor name who examined the victim.

STATUS: ACTIVE ☐
PENDING ☐
INACTIVE ☐
CLOSED ☐


CRIMINAL INVESTIGATOR
ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

264

INVESTIGATIVE REPORT

Case No. 88-4298-261

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: arrive at the residence. They further told me that the entire family was at the funeral home at the time of my visit and further that since the incident that Mr Phillips had taken the electric fence down. Afterwards I went back to the residence where I obtained my camera and photographed the residence, shed and dog pen described earlier. Further a Mr Winfree, app 18 Y.O.A. arrived at the residence and was obviously grief stricken by the death of his younger brother, he took me to the rear of the residence and took out a control box that operated the electric fence and gave it to me and further told me that I was welcome to look around the residence if I wished, further that he was not at the residence the day of the incident but that his uncle (Mr Phillips) was also very upset as to what had happened. Afterwards I took the control Box to my unit where I examined it closely and further photographed it. and afterwards listed all pertinent information as follows:

Produced by: FIDO-SHOCK inc. 5360 National Drive, Knoxville Tenn, 37914.

"Solid State Pet Deterent electric fence controller". Power by 110-120 Volt, 60 Hz Ac. "DANGER" Any Alterations to the designe of this charger may cause seriouse electrical shock. Further showes an intermittent output of current and showes to be used with 12 to 20 quage wire only. Model # SS-750. also below is a square silver sticker with B-6 labeled on it. The device is U/L listed No. 11N0. Serial

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

265

68 A0117

NASHVILLE, TN.....
NATION.....
9/19/88

15

21 Greenbrier 4-year-old dies after shock from fence

From Banner staff reports

GREENBRIER — A 4-year-old Greenbrier boy died Saturday around 7:30 p.m. after he apparently stumbled into an electric fence and was severely shocked, according to Robertson County Sheriff's deputy Charles Hillard.

The child, Steven C. Winfree, and his sister were visiting the home of Walter Phillip of Dividing Ridge Road in Greenbrier about 23 miles north of Nashville.

Phillip told police the boy was playing with some other children about 5:30 p.m. Saturday in the backyard when he

stumbled into an electric fence inside a dog pen.

The 24-volt electric fence is used, Phillip said, to keep the dogs away from the fence surrounding the pen.

The child, the son of Steven Carl and Wanda Winfree of Maple Street, was taken by the Lifeflight helicopter to Vanderbilt University Medical Center, where he later died.

While on their way to the scene, Robertson County Emergency Medical Service workers notified Vanderbilt about the situation.

The emergency helicopter flew to the scene and landed in the neighborhood, according to

Robertson County Emergency Service Director Bob Fletcher.

"The sheriff's deputy was already on the scene so they started CPR," Fletcher said.

Winfree's body has been taken to Nashville General Hospital to be examined, Vanderbilt officials said today.

Robertson County Chief Deputy Milton Frederick said the department is still investigating the incident.

"We'll probably have a comprehensive report later today," Frederick said.

Frederick said officials are investigating to see if the fence was operating properly when the child fell on it.

EPO.7

Oct 31 1988

881115000 2060

266

ACCIDENT INVESTIGATION REQUEST FORM

Document Number 28A0117A1

Date of Incident 9/17/88 Category I.D. SECT 1519F9

Follow-up Requested ☐ Hazard Analysis ☐ Section 15 ☒

Type Follow-up Requested ☐ Telephone Call ☐ On-Site ☐

Headquarters Contact Dave Johnson 492-6608

Assignment Message Conduct an investigation of the electric fence related death reported in the attached news article. Contact local officials for information on the product, the accident scenario and the cause (malfunction of unit). Obtain a copy of any report regarding this death, including that of any analysis of the product.

Person(s) to Contact Co. Sheriff Det. Charles Wilson
Robertson, Co. Miss D. City
Michael Anderson
Greenburg, Tex

Guideline _____

Requested By D. Johnson

Task Number 88115CCC 2060

Assigned to Chi Date 11/15/88

File/mailed

31 JAN 1989

DJ
SECT 15 1989

1. CASE NO. 881115CCC2060		2. INVESTIGATOR'S ID 8 9 3 5		3. OFFICE CODE 8 3 8		EPIDEMIOLOGIC INVESTIGATION REPORT	
4. DATE OF ACCIDENT YR MO DAY 8 8 0 9 1 7		5. DATE INVESTIGATION INITIATED YR MO DAY 8 8 1 2 0 6					
6. SYNOPSIS OF ACCIDENT OR COMPLAINT <u>A four year old male victim died of Cardiac/Respiratory arrest after receiving an electric shock by falling across a electric dog fence. The victim was playing "frisby" with his cousin and was attempting to retrieve the toy which had inadvertently gone over the fence. Examination of the controller for the electric dog fence identified two fuses which were four times the strength recommended for use by the manufacturer.</u>							
7. LOCATION (Home, school, etc.) Home - Back Yard		8. CITY Ridge Top		9. STATE Tennessee			
10A. FIRST PRODUCT Electric Wire		11A. TRADE/BRAND NAME, MODEL NUMBER, MANUFACTURER & ADDRESS "FIDO-SHOCK", Model #SS-750 FI-Shock Inc., 5360 National Drive, Knoxville, TN					
10B. SECOND PRODUCT Fence		11B. TRADE/BRAND NAME, MODEL NUMBER, MANUFACTURER & ADDRESS N/A		FEB 1 1989			
12. AGE OF VICTIM 0 0 4		13. SEX (Use numerical code) MALE - 1 FEMALE - 2 UNKNOWN - 3 1		14. DISPOSITION Fatality		15. INJURY DIAGNOSIS Electric Shock	
16. BODY PART All Parts		17. RESPONDENT(S) (Mother, Friend) Police Detective		18. TYPE INVESTIGATION ON SITE 1 TELEPHONE 2 OTHER 3 1		19. TIME SPENT 1 4 0	
20. ATTACHMENTS Multiple		21. CASE SOURCE Newspaper		22. REVIEWED BY 8 2 9 8		YR MO DAY 8 9 0 1 2 5	
23. PERMISSION TO DISCLOSE NAMES (NON-HESS CASES ONLY) CPSC MAY DISCLOSE MY NAME <input type="checkbox"/> CPSC MAY NOT DISCLOSE MY NAME <input checked="" type="checkbox"/>							
24. NARRATIVE (See Instructions on Other Side)				25. REGIONAL OFFICE DIRECTOR REVIEW DATE			

(USE OTHER SIDE AND ADDITIONAL SHEETS IF NECESSARY)

268

881115CCC2060

Pre-Accident:

This investigation was conducted in response to a newspaper report that a four year old male child died as a result of injuries received after he fell across a electric dog fence. Information gained in this case was obtained through an on-scene examination of the accident area, and conversations with the victim's aunt and police officials.

Victim's aunt stated that her husband purchased the entire electric dog fence system approximately one year ago at Lowe's Building and Supply, Clarksville, Tennessee. The electric fence was installed by victim's uncle inside of an existing dog compound that measured approximately 36 feet by 42 feet. The purpose of the electric fence was to prevent two Chow dogs from jumping up on the inside of the pre-existing fence and climbing out of their enclosure. The electric dog fence consisted of two strands of electrical fence wire attached to wooden stakes approximately one foot from the inside of the pre-existing fence. The bottom wire of the electric fence was approximately one foot from the ground and the top wire was approximately three feet from the ground.

Victim's aunt stated that the victim was approximately four feet tall and weighed approximately fifty pounds. Victim had brown hair and brown eyes. Victim was a very active child and had a history of bronchitis. Victim's mother brought the victim to their house in order for him to play with his cousin. Victim was wearing tennis shoes, a pull-over "T" shirt and short pants at the time of the accident. Victim's mother was not present at the time of the accident.

At approximately 5:15 pm, September 17, 1988, victim was playing "Frisby" with his three year old cousin in the back yard. Weather conditions were cloudy and overcast, and the temperature was approximately 75 degrees fahrenheit. It had rained earlier in the day and the ground was still wet.

Accident:

At approximately 5:30 pm, victim's uncle, who was sitting on his back porch, noticed that the victim was no longer in sight. Victim was discovered by his uncle inside of the dog compound slumped across the electric dog fence, but not in contact with the outside pre-existing fence. Victim was unconscious and a burn mark was observed behind his right knee.

269

881115CCC2060

Post Accident:

Victim's uncle immediately picked up victim (without being shocked) and carried him into the house. A county police patrol responded to the location and attempted to revive the victim by Cardio Pulmonary Resuscitation (CPR). Victim was subsequently transported to Vanderbilt Hospital, Nashville, Tennessee where he was pronounced dead. Cause of death, as reported by the medical examiner, was identified as cardio/respiratory arrest due to electric shock and the manner of death identified as accidental.

Victim's uncle subsequently removed both strands of the electric dog fence and threw them away, however, the electrical control box was not discarded and was taken by county police detectives for examination. Their examination revealed the existence of two fuses, 1/2 Amp, 250 Volts each, inserted in the control box. It was observed from the labeling on the control box panel that both of the fuses that were used in the control box were four times the strength recommended by the manufacturer. Victim's aunt stated that when her husband was putting up the fence he attempted to use the fuses that came with the electric fence system, however, each time the recommended fuses were used the fuses would "blow" as soon as power was supplied to the control box. Victim's aunt stated that the only way to get the fence to work was to use stronger fuses.

A request was made by the CPSC investigator to obtain the control box for a sample and examination however, due to possible future litigation, the request was refused.

Telephonic contact with Lowe's Building and Supply, Clarksville, Tennessee revealed that they no longer had the Fido-Shock, pet deterrent in stock, and they have not experienced any product complaints

Standards:

No voluntary or mandatory standards information was observed on the product.

Product Identification:

The product is an electrical control box enclosed in black plastic and generally mounted indoors, on the walls of a building. Product is manufactured by Fi-SHOCK, Inc., 5360 National Drive, Knoxville, Tennessee, 37914. Additional labeling states: FIDO-SHOCK, Solid State Pet Deterrent, Electric Fence Controller. The controller is powered by 110-120 Volt 60Hz ac. Additional warnings include: "DANGER" any alterations to the design of this charger may cause serious electrical shock. At top center of the box a warning states "use one sixteenth Amp time delay fuses only"

No assembly instructions or additional warnings information was available.


881115CCC2060

Attachments:

1. Photographs
2. Medical Examiners Investigative Report, dtd 9/18/88
3. Robertson County Offense Report, dtd 9/17/88
4. Investigation Report, dtd 9/19/88
5. Newspaper Article, 9/19/88 (Nashville Banner)
6. Copy of CPSC Assignment

CPSC EXHIBIT 1 DATE 12/07/88
FIRM IDI # 881115CCC2060

NAME David M. Galanti, Invest. CPSC



ELECTRIC
CONTROLLER



CPSC EXHIBIT	2	DATE	12/07/88
FIRM	IDI# 881115CCC2060		
NAME David M. Galanti, Invest. CPSC			



N.E. CORNER OF
Dog compound




INSIDE pre-existing
FENCE where VICTIM
WAS FOUND

REPORT OF INVESTIGATION BY COUNTY MEDICAL EXAMINER

Marks and Wounds _____

Cyanosis



PROBABLE CAUSE OF DEATH	MANNER OF DEATH	DISPOSITION OF CASE
<i>Cardio-Peep Arrest due to Electric Shock from Dog Fence.</i>	(Check one only) Accident <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Suicide <input type="checkbox"/> Unknown <input type="checkbox"/> Homicide <input type="checkbox"/> Pending <input type="checkbox"/>	1. Not a medical examiner case <input type="checkbox"/> 2. Autopsy requested Yes <input type="checkbox"/> No <input type="checkbox"/> Autopsy ordered Yes <input type="checkbox"/> No <input type="checkbox"/> Pathologist _____

I hereby declare that after receiving notice of the death described herein I took charge of the body and made inquiries regarding the cause of death in accordance with Section 38-701-38-714 Tennessee Code Annotated; and that the information contained herein regarding such death is true and correct to the best of my knowledge and belief.

9-18-88 Dorothy Cuthbertson M.D. E. Simpkins M.D.
Date County of Appointment Signature of County Medical Examiner

ATTACHMENT 2

1064

PAGE 1

OFFENSE

PAGE 1-OF 1

2. Classification ACCIDENTAL DEATH		TH 0740010	DATE 09-17-88	TIME 1737
1. Name JUDGE RD LAST RES. UN D-WALKER		4. Zone 2	5. Date/Time Occurred 09-17-88 1737	6. Date/Time Police Arrived 09-17-88 1737
7. Sex N/A	8. Race N/A	9. D.O.B. N/A	10. Home Address N/A	
11. Business Phone N/A	12. Person Arrested N/A	13. Sex N/A	14. Race N/A	15. D.O.B. N/A
16. Home Address N/A	17. Sex N/A	18. Race N/A	19. D.O.B. N/A	20. Home Address N/A
VEHICLE				
a. License No. (LIC) NONE	b. State NONE	c. Year NONE	d. Type NONE	e. Vehicle Identification No. (VIN) NONE
f. Year NONE	g. Make NONE	h. Model NONE	i. Other Description or Damage NONE	
21. WEAPON	22. Gen. Description N/A			
23. PROPERTY	24. Description N/A			
25. Reporting Officer 436AT	26. Badge 536	27. Unit 536	28. Approving Supervisor N/A	
29. NARRATIVE: Give an information necessary. Tell who, what, when, where, why and how the incident occurred. Give detailed descriptions of any suspects. All witnesses' names, sex, race, D.O.B., addresses and phone numbers should be recorded. If a juvenile is involved in any way in this offense, list his parents' or guardians' names, addresses and phone numbers as well as the school he attends. ON SEPT. 17-88 AT 5:37 PM. WHILE ON DIVIDEN RIDGE ROAD A SUBJECT FLAGGED ME DOWN AND STATED THAT THEIR'S A BOY THATS DOWN AND WAS STOP BREATHING. AT THIS TIME MYSELF AND OFFICER RANDY CAUENDER WENT INSIDE THE RESIDENT AND FOUND A WHITE MALE JUVENILE IN THE FLOOR WITH SEVERAL SUBJECTS WERE AROUND THE KID. AT THIS TIME A NEIGHBOR STATED THAT THE YOUNG BOY GOT INTO AN ELECTRIC FENCE THAT WAS INSIDE THE DOG PEN. OFFICE CAUENDER AND ANOTHER SUBJECT IDENTIFIED AS PAUL OLLAN STARTED C.P.R. ON THE SUBJECT WHILE I DISPATCHED THE AMBULANCE SERVICE, RIDGETOP FIRE DEPT., AND UNDERBILT'S LIFE-FLIGHT TO THE SCENE. APPROX 15 MIN LATER THE AMBULANCE ARRIVED AND TOOK OVER C.P.R. UNTIL LIFE FLIGHT ARRIVED. JUST A SHORT TIME AFTER LIFE FLIGHT WAS IN ROUTE TO UNDERBILT HOSPITAL WITH THE SUBJECT. THE OWNER OF THE RESIDENT STATED THAT THE MOTHER OF THE 4 YEAR OLD BOY, [REDACTED] LEFT THE CHILD AT HIS RESIDENT WHILE SHE WENT BACK HOME. [REDACTED] STATED THAT THE KIDS WERE OUTSIDE PLAYING AND THEY NOTICED THAT THEY DID NOT SEE [REDACTED] (THE VICTIM) PLAYING WITH THE OTHER KIDS. THEY GOT UP AND LOOKED OUT AND SAW [REDACTED] LYING OVER INSIDE THE DOG PEN OVER THE ELECTRIC FENCE. END OF PAGE ONE				
STATUS	Active <input type="checkbox"/>	Pending <input type="checkbox"/>	Inactive <input type="checkbox"/>	Closed <input type="checkbox"/>
Assigned To	Authority		Date	
NCIC/TIES Entries Have Been Made By:	Date	All Items Have Been Cleared From NCIC/TIES By:		Date

OFFENSE REPORT

PAGE 2-OF-1

1. Offense INFORMATION		2. Classification ACCIDENTAL DEATH		3. TN 0742000	4. Year 88	5. Month 09	6. Day 17	7. Time 1737																			
3. Location of Incident PAGE 1 OF 1				4. Zone 2	5. Date/Time Occurred 09-07-88		6. Date/Time Police Arrived 09-17-88																				
7. Victim PAGE 1 OF 1	Sex	Race	D.O.B.	8. Home Address			9. Phone																				
10. Business Address			11. Business Phone		12. Person Arrested			Sex	Race	D.O.B.																	
13. Complaint			Sex	Race	D.O.B.	14. Home Address			15. Phone																		
16. Witness' Name			Sex	Race	D.O.B.	17. Home Address			18. Phone																		
19. VEHICLE			a. License No. (LIC)	b. State	c. Year	d. Type	e. Vehicle Identification No. (VIN)		f. Year	g. Make	h. Model																
i. Style		j. Color	k. Other Description or Damage																								
20. WEAPON		Gen. Description		Serial # (SN)		Make		Caliber		Type																	
21. PROPERTY		Description									22. Total Value																
23. Reporting Officer WILLARD, CHARLES				Badge 567		Unit 540		24. Approving Supervisor																			
24. NARRATIVE: Give All Information Necessary, Tell Who, What, When, Where, Why And How The Incident Occurred. Give Detailed Descriptions Of Any Suspects. All Witness' Names, Sex, Race, D.O.B., Addresses And Phone Numbers Should Be Recorded. If A Juvenile Is Involved In Any Way In This Offense, List His Parents' Or Guardians' Names, Addresses And Phone Numbers As Well As The School He Attends.																											
<p>MR. WILLARD RAY, AUNT DICK, GOT THE BUS AND BROUGHT HIM INSIDE THE RESIDENT JUST AS WE PULLED INTO THE DRIVEWAY. MR. WILLARD AND I WENT OUT TO THE DOG PEN TO LOOK AT THE FENCE AND HE STATED THAT THE FENCE WAS A 24 VOLT ELECTRIC FENCE THAT WAS PUT INSIDE THE DOG PEN TO KEEP THE DOGS AWAY FROM THE MAIN FENCE. THE MAIN FENCE STANDS ABOUT 3 1/2 FT. WITH THE ELECTRIC FENCE ABOUT A FOOT FROM THE GROUND ON THE INSIDE.</p> <p>THE MOTHER, WILLARD WAS NOTIFIED AND WAS TRANSPORTED TO VANDERBILT HOSPITAL BY HER BROTHER. WILLARD DAUGHTER WAS AT THE RESIDENT AT THE TIME WITH WILLARD.</p> <p>MYSELF AND DEP. CAWENDER LEFT THE SCENE AT 6:32 P.M. AND AT 7:19 I RECEIVED A CALL FROM VANDERBILT HOSPITAL AND WAS TOLD THAT THE 4 YEAR OLD WHITE MALE JUVENILE DID NOT MAKE IT.</p>																											
<table border="1"> <tr> <td>STATUS</td> <td>Active <input type="checkbox"/></td> <td>Pending <input type="checkbox"/></td> <td>Inactive <input type="checkbox"/></td> <td>Closed <input type="checkbox"/></td> <td>Assigned To</td> <td>Authority</td> <td>Date</td> </tr> <tr> <td colspan="4">NCIC/TIES Entries Have Been Made By:</td> <td>Date</td> <td colspan="2">All Items Have Been Cleared From NCIC/TIES By:</td> <td>Date</td> </tr> </table>												STATUS	Active <input type="checkbox"/>	Pending <input type="checkbox"/>	Inactive <input type="checkbox"/>	Closed <input type="checkbox"/>	Assigned To	Authority	Date	NCIC/TIES Entries Have Been Made By:				Date	All Items Have Been Cleared From NCIC/TIES By:		Date
STATUS	Active <input type="checkbox"/>	Pending <input type="checkbox"/>	Inactive <input type="checkbox"/>	Closed <input type="checkbox"/>	Assigned To	Authority	Date																				
NCIC/TIES Entries Have Been Made By:				Date	All Items Have Been Cleared From NCIC/TIES By:		Date																				

INVESTIGATIVE REPORT

Case No. XXXXXXXXXX				
TN0740000	88	09	17	1737
QRI	YEAR	MONTH	DAY	TIME

OFFENSE: Homicide / AccidentalDATE & TIME OCCURED: 9/17/88 @ 1737VICTIM: ~~XXXXXXXXXXXXXXXXXXXX~~ADDRESS: ~~XXXXXXXXXXXXXXXXXXXX~~PHONE NUMBER: None

NARRATIVE: On 9/19/88, I recieved a copy of an offense report from Det Sgt Green, the report showed that the above victim had died from an electrical shock from a fence at the ~~XXXXXXXXXX~~ residence located on dividing ridge road in Ridgetop Robertson County Tenn. A summary shown on the report by Patrol Sgt Hilliard showed that he and officer Cavender where on patrol in the area when they where flagged to stop by a subject on a three wheeler and told that a young boy had stoped breathing at the Phillips residence, according to the report they arrived at the residence to find the child unconcious and found him not to be breathing where Deputy Cavender and a niighbor began C.P.R. on the child while Sgt Hilliard Called for further assistance. Hilliard further revealed in his report that the victims mother ~~XXXXXX~~ ~~XXXXXX~~ dropped the child off at the residence earlier that day and that he and the other children where playing in the back yard area of the residence when a short while later he (~~XXXXXXXXXXXX~~) noticed that the victim was not playing with the other children when he went to investigaye he found the child on the inside of the dog pen laying over the electric fence that lines the inner side of the dog pen. At that Time the child was taken into the house by family members and afterwards he was flown out to Vanderbuilt Hospitol by Life Flight. Hilliards report further stated that he recieved a call

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

[Signature]
 CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88

ATTACHMENT 4

277

INVESTIGATIVE REPORTCase No.

TN0740000				
ORI	YEAR	MONTH	DAY	TIME

OFFENSE: _____

DATE & TIME OCCURED: _____

VICTIM: _____

ADDRESS: _____

PHONE NUMBER: _____

NARRATIVE: from officials (unknown accordind to the report) from Vanderbuilt Hospital that told him that the child died.

..... INVESTIGATORS NOTE : On 9/19/88 I recieved this information as previously described, an investigator was not notified at the time of the incident therefor the following information was obtained by myself during a follow up investigation some 48 hours later.

On 9/19/88 I furter spoke with officer Cavender who also was at the scene of the incident, he could not add any further information other than it appeared that ~~the residents~~ or someone at the residence had possibly been consuming some alcoholic type beverages for there was a couple of budweiser cans setting on a table at the rear porch area where they said they where setting, Further that Mr looked according to the reddish complexion to the face to have had a few beers but did not appear to Cavender to be intoxicated. Further that he (Cavender) observed the dog pen and from his memory he told me that he belives that there where two stands of electrical fence wire around the inner side of the pen, further that one of the m was approximatly one foot from the ground, Cavender further told me that he observed a burn or bruise mark on the leg of the child tha t appeared to have been caused by a wire or some type. He further told me that there was no other marks such as bruising or laceration s or contusions that he saw on the body of the child and that he .

STATUS: ACTIVE ☐
 PENDING ☐
 INACTIVE ☐
 CLOSED ☐

CRIMINAL INVESTIGATOR
 ROBERTSON COUNTY SHERIFFS DEPT

DATE OF THIS REPORT 9/19/88